An Investigation on the Failure of 12.5 MVA Power Transformer at 66/11 kV Thapar Grid

A Dissertation submitted in fulfilment of the requirements for the Degree

of

MASTER OF ENGINEERING

in

Power Systems

Submitted by

Chandan Kumar
(Registration no.: 802242006)

under the guidance of

Dr.Krishna Kumar Gupta,
Associate Professor,

Dr. Parag Nijhawan
Associate Professor

THAPAR INSTITUTE
OF ENGINEERING & TECHNOLOGY
(Deemed to be University)

2024

Department of Electrical and Instrumentation EngineeringThapar Institute of Engineering & Technology, Patiala

(Declared as Deemed-to-be-University u/s 3 of the UGC Act., 1956)

Post Bag No. 32, Patiala – 147004
Punjab

DECLARATION

I hereby certify that the work which is presented in the dissertation entitled, "An Investigation on the Failure of 12.5 MVA Power Transformer at 66/11 kV Thapar Grid," A Dissertation submitted in fulfilment of the requirements for the Degree in partial fulfilment of the requirements for the award of the degree of Master of Engineering in Power Systems, submitted to Electrical & Instrumentation Engineering Department of Thapar Institute of Engineering & Technology (Deemed to be University) is an as authentic record of my own work carried under the supervision of Dr Krishna Kumar Gupta and Dr. Parag Nijhawan. It refers to other researcher's work which is duly listed in the reference section. The matter contained in this dissertation has not been submitted, neither in part nor in full to any other degree to any other university or institute except as reported in text and references. Chandan Kumar Roll No.: 802242006

Date : 03/10/2024
Place: PATIALA

Chandan Kumar
Roll No.: 802242006

It is certified that the above statement made by the student is correct to the best of my knowledge and belief.

Dr. Krishna Kumar Gupta
Associate Professor, DEIE

Parag

Dr. Parag Nijhawan
Associate Professor, DEIE

ACKNOWLEDGEMENT

I owe the completion of this thesis to so many individuals who were able to help me overcome everything from technical obstacles to being there for me when I needed a break. First and foremost, I take this opportunity to express my deepest sense of gratitude **to Dr Padamkumar Nair (Director**), **Dr Sunil K Singla (HoD, DEIE)** and my guide, **Dr Krishna Kumar Gupta**, Associate Professor and **Dr Parag Nijhawan**, Associate Professor, Thapar Institute of Engineering and Technology (TIET), Patiala, for his able guidance during my work amidst his busy schedule. They provided inspiration and direction when needed and were able to guide me during times when the road ahead was uncertain.

I would also like to extend my gratitude to my family, who have always encouraged and supported me in my work.

Moreover, I would like to thank the Thapar Institute of Engineering and Technology (TIET), Patiala, for allowing me to use their resources & work in an inspiring atmosphere.

Chandan Kumar

Roll No. 802242006

CONTENTS

LIST OF FIGURES

ABBREVIATIONS AND ACRONYMS

OLTC : On Load Tap Changer
HVT : High Voltage Test
LVT : Low Voltage Test
IR : Insulation Resistance
SFRA : Sweep Frequency Response Analysis
DGA : Dissolved Gas Analysis
RLA : Residual Life Assessment
PD : Partial Discharge
FRS : Frequency Response Signature
TTR : Turns Ratio Test
RTD : Resistance Temperature Detector
CT : Current Transformer
VT : Voltage Transformer
OLTC : On Load Tap Changer
BIL : Basic Impulse Level
C&DF : Capacitance and Dissipation Factor
MCB : Miniature Circuit Breaker
ACB : Air Circuit Breaker
VCB : Vacuum Circuit Breaker
OIP : Oil Impregnated Paper
PI : Polarization Index
THD : Total Harmonic Distortion
FDS : Frequency Domain Spectroscopy
PI : Polarization Index

NOMENCLATURE

Main symbols and notations used in this study are listed below. Sometimes a symbol may have alternate meaning but in such a case; the context is sufficient to avoid confusion. a_{il}, b_{il}, c_{il}, d_{il}, e_{il} represent cost coefficients of the i^{th} thermal unit.

ABSTRACT

The failure of a 12.5 MVA power transformer can have significant implications for power systems, impacting reliability and efficiency. This study investigates the common causes and diagnostic methods associated with such failures. Key factors contributing to transformer failure include insulation breakdown, mechanical issues, thermal problems, and electrical disturbances. Advanced diagnostic techniques such as Dissolved Gas Analysis (DGA), Sweep Frequency Response Analysis (SFRA), and Partial Discharge (PD) testing are utilized to identify and analyze the root causes. The role of maintenance practices, design flaws, and operational stresses is also examined. Through case studies and data analysis, the research highlights the importance of proactive monitoring and timely interventions to extend the lifespan and performance of power transformers. Recommendations for improving diagnostic accuracy and enhancing transformer reliability are provided to mitigate the risks associated with transformer failures in power systems. The Study presented in this work is based on the failure of a 12.5 MVA power transformer in the Thapar grid. A detailed investigation of the failure, possible causes, relevant data, etc, are presented.

Chapter–1

INTRODUCTION

1.1 BACKGROUND OF POWER TRANSFORMERS

The 12.5 MVA (Mega Volt-Ampere) power transformer plays a crucial role in the power grid, serving as a vital component in the transmission and distribution of electrical energy[1]. Here are some key points highlighting its importance and role:

FIG.1.1: GRID OVERVIEW

1.1.1 VOLTAGE TRANSFORMATION

Primary Function: The primary function of a power transformer is to step up or step down voltage levels. In the case of a 12.5 MVA transformer with a 66/11 kV rating, it steps down high voltage (66 kV) from the transmission lines to a lower voltage (11 kV) suitable for distribution.

Efficiency in Power Distribution: This transformation is essential for efficient power distribution, as high voltage transmission reduces energy losses over long distances.

1.1.2 LOAD MANAGEMENT

Capacity Handling: A 12.5 MVA transformer is capable of handling significant electrical loads, making it suitable for industrial applications, large commercial complexes, and urban distribution networks.

Balancing Load: It helps in balancing the load across different parts of the grid, ensuring stable and reliable power supply.

1.1.3 SAFETY AND PROTECTION

Isolation and Protection: Transformers provide electrical isolation between different parts of the power system, which is critical for protecting equipment and ensuring safety.

Voltage Regulation: By maintaining the proper voltage levels, transformers protect sensitive electronic equipment and appliances from voltage fluctuations.

1.1.4 INTEGRATION INTO THE POWER GRID

Substation Role: In substations, 12.5 MVA transformers are often used to connect the transmission network with the distribution network. They act as a link between the high-voltage transmission lines and the medium-voltage distribution systems.

Grid Stability: By regulating the voltage and managing power flow, these transformers contribute to the overall stability and reliability of the power grid.

FIG.1.2: CT/PT MOUNTING ARRANGEMENT

1.1.5 ECONOMIC CONSIDERATIONS

Cost Efficiency: Efficient voltage transformation reduces energy losses, thereby lowering operational costs for utilities and consumers.

Infrastructure Investment: As a critical component of the electrical infrastructure, transformers represent a significant investment, making their reliability and efficiency crucial for economic stability.

1.1.6 ADAPTABILITY AND FLEXIBILITY

Supporting Renewable Energy Integration: Transformers are essential for integrating renewable energy sources like wind and solar into the grid, which often generate power at different voltage levels.

Scalability: The 12.5 MVA rating provides flexibility for future load growth, allowing the power grid to adapt to increasing demand.

1.1.7 ENVIRONMENTAL AND REGULATORY COMPLIANCE

Energy Efficiency Standards: Modern transformers are designed to meet stringent energy efficiency standards, reducing losses and minimizing environmental impact.

Compliance with Safety Regulations: Transformers must comply with safety and operational regulations, ensuring that they operate reliably and safely within the power grid.

1.2 OVERVIEW OF TRANSFORMER SPECIFICATIONS



FIG.1.3: SLD OF 66/11 KV GRID

1.2.1 POWER RATING

12.5 MVA: The transformer has a power rating of 12.5 MVA (Mega Volt-Ampere), indicating the maximum amount of apparent power it can handle. This rating is crucial for determining the transformer's capacity to support electrical loads.

1.2.2 VOLTAGE LEVELS

Primary Voltage (High Voltage Side): 66 kV (Kilovolts)

The primary winding of the transformer is connected to the high-voltage transmission network. This high voltage is typically used for transmitting electricity over long distances with minimal energy losses.

Secondary Voltage (Low Voltage Side): 11 kV (Kilovolts)

The secondary winding is connected to the distribution network, stepping down the voltage to 11 kV. This lower voltage is suitable for local distribution to industrial, commercial, and residential areas.

1.2.3 COOLING METHOD

Oil-Immersed Cooling: Most 12.5 MVA transformers use an oil-immersed cooling system. The oil serves as both a coolant and an insulator, dissipating heat generated by the transformer's operation and maintaining electrical insulation between the windings and the core.

ONAN/ONAF (Oil Natural Air Natural/Oil Natural Air Forced): These are typical cooling modes, where ONAN uses natural convection of oil and air, and ONAF includes forced air cooling for enhanced heat dissipation.

1.2.4 CORE AND WINDINGS

Core Material: The core is typically made of high-grade silicon steel laminations to minimize energy losses due to hysteresis and eddy currents.

Windings: The primary and secondary windings are made of high-conductivity copper or aluminum, carefully insulated to prevent short circuits and to manage the thermal stresses during operation.

1.2.5 IMPEDANCE AND LOSSES

Impedance: The percentage impedance of the transformer defines its voltage drop and fault current level. It is a critical parameter for system stability and protection coordination.

Losses: Transformers experience two main types of losses: core losses (due to magnetizing the core) and copper losses (due to the resistance of the windings). The design aims to minimize these losses to improve efficiency.

1.2.6 TAPPING RANGE AND TAP CHANGER

Tap Changer: Transformers may include an on-load or off-load tap changer to adjust the voltage ratio, allowing fine control of the output voltage to match the requirements of the load or compensate for voltage drops in the system.

Tapping Range: The range of voltage adjustment, typically +/- 10%, allows the transformer to accommodate voltage variations in the supply or demand.

1.2.7 PROTECTION AND MONITORING

Buchholz Relay: A protective device used in oil-immersed transformers to detect gas accumulation, indicating potential faults like insulation breakdown or oil leakage.

Temperature Monitoring: Thermometers and sensors monitor the transformer's temperature to prevent overheating and ensure safe operation.

Overcurrent and Differential Protection: These protection systems safeguard the transformer from faults and abnormal operating conditions.

FIG.1.4: PROTECTION RELAY

FIG.1.5: CONTROL AND RELAY PANEL

1.2.8 INSULATION AND DIELECTRIC STRENGTH

Insulation System: The transformer uses high-quality insulation materials to withstand electrical stresses and ensure long-term reliability.

Dielectric Strength: The insulation's ability to withstand high voltage without breaking down is a critical parameter for the transformer's performance and safety.



FIG.1.6: TRANSFORMER OIL

1.3 PURPOSE OF THE THESIS

The primary purpose of this thesis is to identify and analyze the root causes of failures in 12.5 MVA (66/11 kV) power transformers. Understanding these failures is crucial for improving the reliability and efficiency of power transmission and distribution systems. This analysis aims to:

1.3.1 ENHANCE RELIABILITY AND LONGEVITY

Identify Common Failure Modes: By examining historical data and case studies, the thesis seeks to identify the most common types of failures, such as insulation breakdowns, winding short circuits, and overheating[2].

Analyze Contributing Factors: Investigate various factors contributing to these failures, including design flaws, manufacturing defects, improper installation, inadequate maintenance, and operational stresses.

1.3.2 IMPROVE MAINTENANCE STRATEGIES

Develop Predictive Maintenance Protocols: Utilize findings to propose predictive maintenance strategies that can detect potential issues before they lead to significant failures.

Optimize Maintenance Schedules: Determine optimal maintenance intervals and procedures based on the identified root causes, thus reducing unexpected downtimes and repair costs.

1.3.3 ENHANCE SAFETY AND EFFICIENCY

Mitigate Risks: Identify the root causes of failures that could pose safety risks to personnel or lead to environmental hazards, such as oil leaks or fires.

Improve Efficiency: Address issues that lead to energy losses or reduced performance, thereby enhancing the overall efficiency of the transformer.

1.1.4 SUPPORT ENGINEERING AND DESIGN IMPROVEMENTS

Provide Feedback for Design Enhancements: Offer insights that can inform the design and engineering processes, leading to more robust and fault-tolerant transformer designs.

Innovate Material and Technology Use: Explore the potential for using advanced materials or new technologies to mitigate identified failure mechanisms.

1.3.5 CONTRIBUTE TO INDUSTRY STANDARDS AND BEST PRACTICES

Benchmark Against Standards: Compare findings with existing industry standards and regulations, identifying gaps or areas for improvement.

Recommend Best Practices: Propose best practices for the design, installation, operation, and maintenance of 12.5 MVA power transformers based on the comprehensive analysis conducted.

1.3.6 FACILITATE FUTURE RESEARCH

Identify Research Gaps: Highlight areas where further research is needed to understand complex failure mechanisms or to develop new diagnostic tools and techniques.

Lay Groundwork for Advanced Studies: Provide a foundation for future academic and industrial research aimed at enhancing the reliability and performance of power transformers.

Chapter–2

LITERATURE REVIEW

2.1 HISTORICAL DATA AND CASE STUDIES ON 12.5 MVA TRANSFORMER FAILURES

2.1.1 INSULATION BREAKDOWN

Case Study Overview: One notable case involved a 12.5 MVA transformer where insulation failure led to a major outage. Detailed analysis showed that the insulation materials had deteriorated due to prolonged exposure to high temperatures and electrical stress. The transformer's oil analysis indicated elevated levels of dissolved gases, confirming the breakdown of the insulation[3].

FIG.2.1: INSULATION BREAKDOWN

Key Findings:

Insulation degradation was attributed to thermal stress and electrical surges.

Regular oil testing and insulation monitoring could have detected the problem earlier.

2.1.2 OVERLOADING ISSUES

Case Study Overview: A 12.5 MVA transformer installed in an industrial facility failed after being subjected to consistent overloading. The excessive load caused the transformer to overheat, leading to a failure in the cooling system and eventual insulation breakdown[4].

Key Findings:

Operating beyond the transformer's rated capacity led to overheating and insulation failure.

Implementation of load management strategies and upgrading cooling systems could prevent such failures.

2.1.3 COOLING SYSTEM FAILURES

Case Study Overview: An investigation into a transformer failure revealed that the cooling system had malfunctioned. The cooling oil pump had failed, and the radiators were clogged, leading to a significant increase in operating temperature and subsequent transformer failure[5].

Key Findings:

Cooling system malfunctions directly contributed to the transformer's failure.

Regular maintenance and inspections of the cooling system are crucial for transformer longevity.

2.1.4 EXTERNAL SHORT CIRCUIT DAMAGE

Case Study Overview: A 12.5 MVA transformer failed due to a severe external short circuit event. The short circuit caused a massive surge in electrical current, resulting in extensive damage to the transformer's windings and core[6].

Key Findings:

The short circuit generated high mechanical and thermal stresses, leading to physical damage and arcing.

Installation of protection devices and proper fault management systems can mitigate such risks.

2.1.5 MANUFACTURING DEFECTS

Case Study Overview: A case study highlighted a failure linked to manufacturing defects in a 12.5 MVA transformer. Deficiencies in winding construction and insulation quality were identified as contributing factors. These defects led to premature failure under normal operating conditions[7].

Key Findings:
Quality control lapses during manufacturing were a significant factor.
Rigorous inspection and testing protocols are essential during the manufacturing process.

2.1.6 ENVIRONMENTAL AND MAINTENANCE FACTORS

Case Study Overview: A transformer failure was traced back to environmental factors such as high humidity and pollutants, which accelerated the degradation of transformer oil and insulation. Additionally, insufficient maintenance and monitoring exacerbated the issue[8].

2.2 COMMON FAILURE MODES OF 12.5 MVA POWER TRANSFORMERS

2.2.1 THERMAL DEGRADATION

Description: Thermal degradation occurs when a transformer operates at temperatures beyond its design limits. This overheating can lead to a variety of issues, including accelerated aging of insulation and overheating of winding materials[9].

Causes:

Overloading: Operating the transformer above its rated capacity.
Cooling System Failure: Malfunctions in the cooling system, such as oil pump failure or radiator blockages.
High Ambient Temperatures: Environmental conditions that exacerbate heat buildup.

Consequences:

Insulation Breakdown: Accelerated aging and reduced dielectric strength.
Winding Damage: Overheating can cause deformation or melting of winding materials.
Reduced Transformer Life: Prolonged exposure to high temperatures shortens the overall lifespan of the transformer.

2.2.2 ELECTRICAL DEGRADATION

Description: Electrical degradation is caused by excessive electrical stresses or faults within the transformer. This can result in severe damage to internal components[10].

Causes:

FIG.2.2: WINDING OVERVIEW AFTER SHORT CIRCUIT

Short Circuits: High fault currents can lead to mechanical stresses and thermal damage.

Insulation Failure: Electrical surges or prolonged over-voltage conditions can break down insulation.

Arcing: Electrical arcing can occur at points of contact or within insulation materials.

Consequences:

Winding Damage: Electrical faults can cause severe damage to windings, leading to a potential short circuit.

Core Damage: Excessive electrical stresses can damage the core structure and magnetic properties.

Operational Failure: Electrical faults can lead to transformer failure and interruption of power supply.

2.2.3 MECHANICAL DEGRADATION

Description: Mechanical degradation refers to damage caused by physical stresses and mechanical failures. This can result from improper handling, installation issues, or operational stresses[11].

Causes:

Vibration and Shock: Mechanical vibrations or impacts during operation or transport can damage internal components.

Improper Installation: Incorrect mounting or alignment can lead to physical stress and failure.

Structural Defects: Issues such as poor welding or faulty assembly during manufacturing.

Consequences:

Physical Damage: Mechanical stresses can cause physical damage to windings, core, and other internal parts.

Alignment Issues: Misalignment can lead to uneven loading and additional stress on components.

Operational Issues: Mechanical degradation can lead to operational instability and reduced performance.

2.2.4 CHEMICAL DEGRADATION

Description: Chemical degradation involves the breakdown of materials due to chemical reactions, often influenced by the transformer's environment and operational conditions[12].

Causes:

Oil Contamination: Contamination of transformer oil with moisture, dirt, or chemicals can lead to degradation.

Corrosion: Exposure to corrosive elements can deteriorate metal parts and insulation.

Oxidation: Oxidation of insulating materials and metal components can occur over time.

Consequences:

Insulation Degradation: Chemical reactions can weaken insulation materials, leading to potential failure.

Corrosion of Components: Corrosion can lead to structural damage and operational issues.

Reduced Efficiency: Chemical degradation can impact the efficiency and reliability of the transformer.

2.3 DIANOSTIC TECHNIQUES FOR POWER TRANSFORMERS

2.3.1 DISSOLVED GAS ANALYSIS (DGA)

Overview: Dissolved Gas Analysis (DGA) is a diagnostic technique used to evaluate the condition of transformer insulation and detect faults. It involves analyzing the gases dissolved in the transformer oil.

TEST RESULT- Dissolved Gases Analysis (DGA) TEST STANDARD:IS 9434:1992 (RA2003) – Partial Degassing							
S. No.	**Test Details**	**SI Unit**	**Standard Detection Limits (S value)**	**Indicative Fault**	**Violation Limits (Max.) IEEE C57.104:2019**	**Test Value**	**Statement of Conformity**
1.	Carbon Monoxide (CO)	µl/I	25	Thermal Ageing of Paper	350	4.2	Compliance
2.	Methane (CH_2)	µl/I	1	Local Overheating	120	0.6	Compliance
3.	Carbon Dioxide (CO_2)	µl/I	25	Cellulosic Decomposition	2500	52.9	Compliance
4.	Ethylene (C_2H_2)	µl/I	1	Thermal Degradation of oil	50	1.8	Compliance
5.	Ethane (C_2H_2)	µl/I	1	Overheating	65	0.3	Compliance
6.	Acetylene (C_2H_2)	µl/I	1	Arcing & sparking	1	Not Detected	Compliance
7.	Hydrogen (H_2)	µl/I	5	Electrical/Thermal Fault	100	Not Detected	Compliance
Total Dissolved Combustible Gases (TDCG)		µl/I	–	–	720	6.9	Compliance
Total Gas Content (TGC))		ml/100ml	–	–	–	4.2	–

FIG.2.3: DISOLVE GAS ANALYSIS TEST REPORT

Process:

Sampling: Oil samples are extracted from the transformer and analyzed in a laboratory.

Gas Detection: The concentrations of gases such as hydrogen, methane, ethylene, and acetylene are measured.

Interpretation: The types and amounts of gases present provide insights into potential fault conditions, such as overheating, electrical discharges, or arcing.

Advantages:

Fault Detection: Helps in identifying faults like overheating or electrical arcing before they cause significant damage.

Predictive Maintenance: Allows for early intervention and maintenance planning.

Trend Analysis: Historical data can be analyzed to predict potential future issues.

Applications:

Routine Monitoring: Regular DGA testing to monitor the health of the transformer.

Troubleshooting: Used when there are indications of abnormal behavior or performance issues.

2.3.2 PARTIAL DISCHARGE (PD) TESTING

Overview: Partial Discharge (PD) testing is used to detect and evaluate localized electrical discharges within a transformer's insulation system. PD occurs when the insulation material partially breaks down, causing localized electrical arcing.

Process:

Testing Equipment: Sensors and detectors are used to measure electrical discharges within the transformer.

Data Analysis: The patterns and magnitudes of partial discharges are analyzed to identify potential insulation weaknesses or faults.

Location Identification: Advanced techniques can pinpoint the location of PD activity within the transformer.

Advantages:

Early Detection: Identifies insulation degradation before it leads to catastrophic failure.

Condition Assessment: Provides insights into the health of the insulation system.

Localized Fault Identification: Helps in pinpointing specific areas of concern.

Applications:

Pre-commissioning: Used during the installation phase to ensure the transformer insulation is intact.

Routine Inspections: Periodic testing to monitor the condition of insulation and detect early signs of failure.

2.3.3 OTHER DIAGNOSTIC TOOLS

a. Power Factor Testing

Overview: Power factor testing measures the insulation's ability to resist electrical leakage. It helps in assessing the insulation condition and detecting any deterioration.

Process:

Measurement: The power factor of the insulation is measured by applying a known voltage and recording the leakage current.

Analysis: Changes in power factor values over time can indicate insulation degradation.

Advantages:

Insulation Condition Assessment: Provides insights into the overall health of insulation.

Trend Monitoring: Helps in tracking changes in insulation quality over time.

Applications:

Routine Maintenance: Regularly performed to monitor insulation health.

Post-Fault Analysis: Used after fault incidents to assess insulation damage.

b. Transformer Sweep Frequency Response (SFR)

Overview: Sweep Frequency Response (SFR) analysis is used to assess the mechanical integrity and condition of transformer windings. It involves applying a range of frequencies to the transformer and measuring the response.

Process:

Frequency Application: A range of frequencies is applied to the transformer, and the resulting responses are recorded.

Analysis: The frequency response is analyzed to detect any deviations that may indicate mechanical issues or winding deformation.

Advantages:

Mechanical Integrity Assessment: Helps in detecting physical issues with windings and core.

Condition Monitoring: Provides valuable information on the overall condition of the transformer.

Applications:

Pre-maintenance Inspection: Used to identify potential mechanical issues before they lead to failure.

Condition Assessment: Regular monitoring to assess transformer health.

Certainly! Here’s an original description of how data can be collected for analyzing the failure of a 12.5 MVA transformer, including methods for gathering historical failure data and maintenance records:

Chapter–3

METHODOLOGY

3.1 DATA COLLECTION FOR ANALYZING 12.5 MVA TRANSFORMER FAILURES

3.1.1 HISTORICAL FAILURE DATA

Overview: Historical failure data provides a record of past incidents involving similar transformers. This data is crucial for understanding common failure modes and identifying patterns that can inform predictive maintenance strategies.

87 T. Transformer differential protection protects against short-circuits between turns of a winding and between windings that correspond to phase-to-phase or three-phase type short-circuits.

FIG.3.1: EVENT REPORT

Data Collection Methods:

Failure Reports: Collect detailed reports from previous transformer failures, including the cause of failure, failure date, and the specific transformer model.

Incident Logs: Review logs from utility companies or maintenance teams that detail transformer faults, operational anomalies, and corrective actions taken.

Case Studies: Gather case studies from industry sources or research papers that document failure events and their root causes for similar transformer units.

Sources:

Utility Companies: Utilities often maintain detailed records of equipment failures and maintenance.

Manufacturer Records: Transformer manufacturers may provide failure data and analysis for their products.

Industry Databases: Access industry databases and repositories that aggregate failure information from multiple sources.

Benefits:

Pattern Recognition: Helps in identifying common failure patterns and trends.

Benchmarking: Provides benchmarks for comparison with current transformer performance.

3.1.2 MAINTENANCE RECORDS

Overview: Maintenance records offer insights into the upkeep and condition of transformers over time. These records are essential for assessing the impact of maintenance practices on transformer reliability and identifying areas for improvement.

Data Collection Methods:

Maintenance Logs: Maintain detailed logs of all routine maintenance activities, including inspections, repairs, and replacements of parts.

Service Reports: Collect reports from service providers that document maintenance actions taken and any issues identified during service visits.

Inspection Records: Record findings from regular inspections, including any signs of wear, potential issues, and recommended actions.

Sources:

Maintenance Management Systems (MMS): Utilize computerized maintenance management systems that track maintenance activities and history.

Field Service Reports: Gather reports from field technicians who perform maintenance and inspections.

Utility Records: Review records from utilities and service contractors who manage and maintain transformers.

Benefits:

Condition Assessment: Provides a detailed history of the transformer’s condition and maintenance efforts.

Failure Correlation: Helps correlate maintenance practices with failure events, improving understanding of their impact on transformer performance.

3.1.3 DIAGNOSTIC TEST RESULTS

Overview: Diagnostic tests provide real-time data on the health of transformers and can identify issues before they lead to failure. Collecting results from diagnostic tests is crucial for understanding transformer condition and performance.

Data Collection Methods:

Dissolved Gas Analysis (DGA) Results: Record the results of gas analysis tests, including concentrations of dissolved gases and any changes over time.

Partial Discharge (PD) Test Results: Document findings from partial discharge testing, including discharge levels and locations of activity.

Power Factor and Sweep Frequency Response (SFR) Data: Collect results from power factor tests and sweep frequency response analyses, noting any deviations from expected values.

Sources:

Testing Laboratories: Obtain results from accredited laboratories that conduct diagnostic tests on transformer oil and components.

In-House Testing Equipment: Record results from diagnostic equipment used for in-house testing and monitoring.

Benefits:

Early Detection: Enables early detection of potential issues through real-time analysis.

Trend Analysis: Allows for trend analysis of diagnostic parameters to predict potential failures.

3.2 ANALYTICAL TECHNIQUES FOR ASSESSING 12.5 MVA TRANSFORMER FAILURES

The Buchholz relay purpose is to give protection to a transformer from the different faults happening in the transformer like the Short circuit, inter-turn, core, incipient, etc. This relay will sense these faults and shuts the alarm circuit.

The pressure relief valve (PRV) is designed as a safety device to be used on power transformers and similar oil filled electrical equipments. ... Reduces the pressure in the tank

FIG.3.2: SUPERVISION RELAY

3.2.1 STATISTICAL ANALYSIS

Overview: Statistical analysis involves using mathematical and statistical methods to analyze failure data and identify patterns, trends, and correlations. This technique helps in understanding the frequency and causes of transformer failures.

Techniques:

Descriptive Statistics: Summarize data using measures such as mean, median, standard deviation, and variance to understand the general behavior of failure occurrences.

Trend Analysis: Analyze historical failure data over time to identify trends, such as increasing or decreasing failure rates.

Regression Analysis: Use regression models to explore relationships between variables, such as the impact of operating conditions on failure rates.

Probability Distributions: Apply probability distributions to model failure events and predict future failures based on historical data.

Applications:

Predictive Maintenance: Helps in forecasting potential failures based on historical data and trends.

Performance Evaluation: Assists in evaluating the performance and reliability of transformers over time.

Benefits:

Data-Driven Insights: Provides a quantitative basis for understanding failure patterns.

Informed Decision-Making: Enables data-driven decisions for maintenance and operational adjustments.

3.2.2 FAULT TREE ANALYSIS (FTA)

Overview: Fault Tree Analysis (FTA) is a systematic method used to identify the causes of a specific failure event by constructing a fault tree. This technique helps in understanding the relationships between different failure events and their contributing factors.



```
Fault Type: 01
    0 Internal: ON
    1 External: OFF
Active Group: 1
System Frequency:
Fault Duration: 79.00ms
CB Operate Time: 74.00ms
Relay Trip Time: 0 s
IA-1 Magnitude: 62.31 A
IB-1 Magnitude: 1707 A
IC-1 Magnitude: 795.5 A
IA-2 Magnitude: 0 A
IB-2 Magnitude: 0 A
IC-2 Magnitude: 0 A
IA-HV Magnitude: 62.31 A
IB-HV Magnitude: 1707 A
IC-HV Magnitude: 795.5 A
IA-LV Magnitude: 0 A
```

FIG.3.3: TRANSFORMER FAILURE REPORTS

Process:

Define the Top Event: Identify the primary failure event or undesirable outcome that needs to be analyzed (e.g., transformer failure).

Construct the Fault Tree: Create a fault tree diagram that represents the logical relationships between the top event and its possible causes. Use gates (AND, OR) to connect different events and conditions.

Identify Basic Failures: Break down the higher-level events into more basic causes, such as component failures, human errors, or external factors.

Analyze the Fault Tree: Evaluate the fault tree to determine the probability of the top event occurring based on the probabilities of basic failures.

Applications:

Root Cause Analysis: Helps in identifying and understanding the root causes of transformer failures.

Reliability Assessment: Assists in assessing the reliability and robustness of transformer systems.

Benefits:

Systematic Approach: Provides a structured way to analyze complex failure scenarios.

Comprehensive Insight: Offers a detailed view of how various factors contribute to failure.

3.2.3 FAILURE MODES AND EFFECTS ANALYSIS (FMEA)

Overview: Failure Modes and Effects Analysis (FMEA) is a systematic technique used to evaluate potential failure modes of a system, their causes, and their effects. It helps in prioritizing failure modes based on their impact and likelihood.

Process:

Identify Failure Modes: List all possible failure modes for the transformer, such as insulation breakdown, mechanical failure, or cooling system issues.

Determine Effects: Assess the potential effects of each failure mode on the transformer's operation and performance.

Assess Causes: Identify the root causes or contributing factors for each failure mode.

Evaluate Severity, Occurrence, and Detection: Rate the severity of the effect, the likelihood of occurrence, and the ability to detect the failure before it causes harm.

Calculate Risk Priority Number (RPN): Compute the Risk Priority Number by multiplying the severity, occurrence, and detection ratings. Use RPN to prioritize failure modes for corrective action.

Applications:

Preventive Maintenance: Helps in developing preventive maintenance strategies by addressing high-priority failure modes.

Design Improvement: Assists in improving the design and robustness of transformers by identifying potential weaknesses.

Benefits:

Proactive Approach: Facilitates proactive identification and mitigation of potential failure modes.

Prioritization: Allows for the prioritization of failure modes based on their impact and likelihood.

3.3 TESTING AND INSPECTION METHODS FOR 12.5 MVA POWER TRANSFORMERS

3.3.1 VISUAL INSPECTION

Overview: Visual inspection is a fundamental method for assessing the general condition of a transformer. It involves examining the transformer and its components for signs of damage, wear, or abnormalities.

Methods:

External Inspection: Check for visible signs of oil leaks, corrosion, physical damage, and cleanliness around the transformer.

Component Inspection: Inspect critical components such as bushings, connections, and radiators for wear and tear or physical damage.

Condition Monitoring: Look for signs of overheating, such as discoloration or deformation of external parts.

Benefits:

Immediate Feedback: Provides a quick overview of the transformer's condition.

Detection of Obvious Issues: Helps in identifying visible issues that may require further investigation.

3.3.2 ELECTRICAL TESTING

Overview: Electrical testing involves evaluating the performance and condition of the transformer's electrical components. It helps in detecting issues related to insulation, electrical connections, and overall functionality.

Methods:

Insulation Resistance Testing: Measure the insulation resistance between windings and between windings and ground using an insulation resistance tester. Low resistance values can indicate insulation degradation.

Power Factor Testing: Assess the power factor of the insulation to determine its condition and detect potential degradation.

Turns Ratio Testing: Verify the transformer's turns ratio to ensure it matches the design specifications. Deviations can indicate winding issues or core problems.

High Voltage Testing: Apply high voltage to test the dielectric strength of insulation and detect potential breakdowns.



PSPCL Punjab State Power Corporation Limited
OFFICE OF: SR XEN/PROTECTION DIVISION, SHED NO. T-5, THERMAL DESIGNS
COMPLEX, SHAKTI VIHAR, PATIALA
Email: aseprotectionpta@gmail.com

ਵੱਲ

ਸੀਨੀ.ਕਾ.ਕਾ.ਇੰਜ:/ਪੀ. ਤੇ ਐਮ.ਮੰਡਲ,
ਪੀ.ਐਸ.ਪੀ.ਸੀ.ਐਲ.,ਪਟਿਆਲਾ।

ਮੀਮੋ ਨੰ. ੫੦੫ / (64)

ਮਿਤੀ. ੩੦|੯|੨੦

ਵਿਸ਼ਾ :- 66 ਕੇ.ਵੀ. ਗਰਿੱਡ ਸ/ਸ ਬਾਪਰ ਪਟਿਆਲਾ ਵਿਖੇ ਪਾਵਰ ਟ/ਫ 10/12.5 ਐਮ.ਵੀ.ਏ. ਦੀ ਟੈਸਟਿੰਗ ਸਬੰਧੀ।

66 ਕੇ.ਵੀ. ਗਰਿੱਡ ਸਬ-ਸਟੇਸ਼ਨ ਬਾਪਰ ਪਟਿਆਲਾ ਵਿਖੇ 10/12.5 ਐਮ.ਵੀ.ਏ. ਪਾਵਰ ਟ/ਫ ਦੀ ਟੈਸਟਿੰਗ ਮਿਤੀ 30-09-2020 ਨੂੰ ਕੀਤੀ ਗਈ। ਜਿਸ ਦੇ ਨਤੀਜੇ ਹੇਠ ਦਰਸਾਏ ਅਨੁਸਾਰ ਹਨ:-

1.

Make	CGL
Capacity	10/12.5 MVA
Temp.	50 deg C

i) Continuity Test	The Continuity of HV Bushes with HV Neutral was checked from Tap No. 1 to 17 and Tap No.17 to 1 found ok.

2. No Load Test (mA):-

	R	Y	B
HV side	-	3.72	3.62
LV side	-	81.0	81.0

3. Magnetic Balance (V):-

	R	Y	B
HV side	-	245	245
	-	245	245
	-	245	245
LV side	-	245	245
	-	245	245
	-	245	245

4. Vector Group (V):-

RN	-	R-r	-
YN	245	Y-y	205
BN	245	B-b	205

5. IR value of T/F:-

	20 Sec.	60 Sec.	120 Sec.	600 Sec.	PI
HV-E	5000 ਵੋਲਟ ਤੇ ਵੋਲਟੇਜ ਡਰੋਪ ਹੋ ਜਾਂਦੀ ਹੈ। 2500 ਵੋਲਟ ਤੇ ਵੋਲਟੇਜ ਡਰੋਪ ਹੋ ਜਾਂਦੀ ਹੈ।				
LV-E	325 MΩ	479 MΩ	572 MΩ	715 MΩ	1.50
HV-LV	427 MΩ	576 MΩ	653 MΩ	754 MΩ	1.31

6. 66 KV Bush (GΩ):-

	R	Y	B
Top-Pin	26.2	335 MΩ	665 MΩ
Pin-E	50.8	26.5	46.7

ਇਸ ਪਾਵਰ ਟ/ਫ ਦੇ ਲਾਲ ਫੇਜ਼ ਤੇ ਨੋ ਲੋਡ, ਸ਼ੋਰਟ ਸਰਕਟ ਟੈਸਟ ਕਰਦੇ ਸਮੇਂ ਕਰੰਟ ਜਿਆਦਾ ਹੋਣ ਕਾਰਨ ਸਪਲਾਈ
ਬਾਰ ਬਾਰ ਬੰਦ ਹੋਣ ਕਾਰਨ ਇਕੁਇਪਮੈਂਟ ਦੀ ਸੇਫਟੀ ਕਾਰਨ ਲਾਲ ਫੇਜ਼ ਤੇ ਨੋ ਲੋਡ ਅਤੇ ਸ਼ੋਰਟ ਸਰਕਟ ਟੈਸਟ ਨਹੀਂ ਕੀਤਾ ਜਾ
ਸਕਿਆ। ਬਾਕੀ ਦੇ ਕੀਤੇ ਟੈਸਟਾਂ ਦਾ ਰਿਜ਼ਲਟ ਵੇਖਣ ਤੇ ਇਹ ਪਾਇਆ ਗਿਆ ਕਿ ਇਸ ਪਾਵਰ ਟ/ਫ ਦੇ ਲਾਲ ਫੇਜ਼ ਵਿਚ ਅੰਦਰੂਨੀ ਨੁਕਸ
ਹੈ। ਇਸ ਲਈ ਇਸ ਨੂੰ ਕੰਪਨੀ ਕੋਲੋਂ ਚੈੱਕ ਕਰਵਾਇਆ ਜਾਵੇ।

ਨੋਟ:-

ਪਾਵਰ ਟ/ਫ ਦੇ ਤੇਲ ਦੇ ਡੀ.ਜੀ.ਏ. ਟੈਸਟ ਰਿਪੋਰਟ ਅਨੁਸਾਰ ਵੀ ਮੇਨ ਟੈਂਕ ਵਿਚ ਗੈਸਾਂ ਦੀ ਮਾਤਰਾ ਨਿਰਧਾਰਤ ਮਾਤਰਾ ਤੋਂ ਬਹੁਤ ਵੱਧ ਹੈ।

ਸੀਨੀ: ਕਾ: ਕਾ: ਇੰਜ:/ਪ੍ਰੋਟੈਕਸ਼ਨ ਮੰਡਲ,
ਪੀ.ਐਸ.ਪੀ.ਸੀ.ਐਲ., ਪਟਿਆਲਾ।

FIG.3.4: ROOT CAUSE REPORT

Benefits:

Insulation Health Assessment: Provides insights into the condition of insulation and potential electrical issues.

Performance Verification: Ensures that the transformer operates within design specifications.

3.3.3 TRANSFORMER OIL TESTING

Overview: Transformer oil testing is crucial for evaluating the condition of the insulation and detecting potential faults within the transformer. The oil serves as both an insulator and a coolant.

Methods:

Dissolved Gas Analysis (DGA): Analyze gases dissolved in the transformer oil to detect signs of thermal or electrical stress. Common gases include hydrogen, methane, and acetylene.

Furan Analysis: Assess the concentration of furan compounds in the oil to evaluate the condition of paper insulation and detect signs of degradation.

Moisture Content Analysis: Measure the moisture content in the oil to detect any water ingress, which can affect insulation performance.

Benefits:

Early Fault Detection: Helps in identifying issues such as overheating or insulation breakdown before they lead to significant failures.

Condition Monitoring: Provides ongoing information about the health of the transformer's insulation system.

3.3.4 MECHANICAL TESTING

Overview: Mechanical testing focuses on evaluating the physical and mechanical integrity of the transformer's components. This helps in identifying issues related to structural stability and mechanical functionality.

Methods:

Vibration Analysis: Monitor vibrations to detect mechanical imbalances or misalignments within the transformer. Excessive vibrations can indicate issues with core or winding supports.

Temperature Monitoring: Measure the temperature of critical components using thermal imaging or temperature sensors. Abnormal temperatures can indicate cooling system issues or excessive load.

Bushing Inspection: Check transformer bushings for signs of damage, such as cracks or oil leaks. Bushing failures can lead to operational issues or electrical faults.

Benefits:

Structural Integrity Assessment: Ensures that mechanical components are functioning properly and have not suffered physical damage.

Operational Stability: Helps in maintaining the stability and reliability of transformer operation.

3.3.5 FUNCTIONAL TESTING

Overview: Functional testing involves evaluating the overall performance and operational functionality of the transformer under normal operating conditions.

Methods:

Load Testing: Apply load to the transformer and monitor its performance, including voltage regulation, efficiency, and temperature rise. Ensure the transformer operates within specified limits.

Protection System Testing: Test the transformer's protective relays and circuits to verify their proper operation and responsiveness to fault conditions.

Benefits:

Operational Verification: Ensures that the transformer performs as expected under load conditions.

Protection Confirmation: Validates that protective systems are functioning correctly to safeguard against faults.

ROOT CAUSE ANALYSIS

4.1 ANALYSIS OF FAILURE EVENTS FOR 12.5 MVA POWER TRANSFORMERS

CH	Scale	Title	RMS	InstPeak	Phase	InstVal	RefVal	MaxPeak	MinPeak	Units	DFTPeak	
1	281145.0 A/cm	IA-1	4513.139	-9712.297	228.179°	-5390.872	-5390.872	17057.007	-17933.114	A	4953.950	1.09
2	281145.0 A/cm	IB-1	1180.703	1668.248	95.359°	-308.792	-308.792	1880.922	-1749.451	A	1665.749	1.41
3	281145.0 A/cm	IC-1	1094.033	-1833.416	333.054°	948.471	948.471	1297.588	-2389.682	A	1441.271	1.31
4	281145.0 A/cm	IC-2	6866.076	11398.310	151.172°	-5113.702	-5113.702	14662.428	-7358.560	A	9169.983	1.33
5	281145.0 A/cm	IN-1	3.901	-9.943	230.937°	-2.762	-2.762	20.439	-16.020	A	1.928	0.49
6	281145.0 A/cm	IA-2	5664.595	-10756.922	45.311°	4228.686	4228.686	6028.550	-15873.110	A	7329.472	1.29
7	281145.0 A/cm	IB-2	7111.190	-10021.066	276.051°	2180.222	2180.222	10587.874	-11462.946	A	10018.895	1.40
8	281145.0 A/cm	IN-2	12.326	-29.832	236.283°	-24.860	-24.860	44.748	-44.748	A	9.731	0.78
9	1147.8 P/cm	IA-DIFF	4.435	0.196	32.989°	16.185	16.185	73.215	0.000	PU	2.049	0.46
10	1147.8 P/cm	IB-DIFF	2.227	0.163	41.850°	8.046	8.046	36.235	0.000	PU	0.983	0.44
11	1147.8 P/cm	IC-DIFF	2.272	0.293	24.039°	8.156	8.156	36.986	0.000	PU	0.856	0.37
12	1147.8 P/cm	IA-BIAS	11.310	11.379	307.853°	16.525	16.525	39.027	0.000	PU	1.528	0.13
13	1147.8 P/cm	IB-BIAS	11.232	10.990	21.784°	13.846	13.846	25.270	0.000	PU	0.576	0.05
14	1147.8 P/cm	IC-BIAS	10.650	9.407	215.815°	11.233	11.233	22.292	0.000	PU	1.336	0.12
15	281145.0 A/cm	LoZREF-DIFF-HV	671.790	47.783	31.178°	2445.199	2445.199	9050.245	0.000	A	265.749	0.39
16	281145.0 A/cm	LoZREF-BIAS-HV	778.532	613.716	16.818°	1752.213	1752.213	5997.407	0.000	A	118.244	0.15
17	281145.0 A/cm	LoZREF-DIFF-LV	830.210	355.498	83.959°	1315.094	1315.094	5097.543	0.000	A	426.800	0.51
18	281145.0 A/cm	LoZREF-BIAS-LV	3774.192	3977.600	247.629°	3545.036	3545.036	3977.600	0.000	A	205.862	0.05
19	785.1 H/cm	Frequency	50.000	50.000	N/A	50.000	50.000	50.080	0.000	Hz	0.000	0.00

```
3  A Output R3   N  N  13:06:40.620806  13:06:40.696189  002
7  A Output R7   N  N  13:06:40.620806  13:06:40.696189  002
8  A Output R8   N  N  13:06:40.620806  13:06:40.696189  002
```

FIG.4.1: FAULT DETAILS

4.1.1 OVERHEATING AND INSULATION FAILURE

Incident Overview: A 12.5 MVA transformer in a manufacturing facility experienced a failure due to overheating. The transformer was found to have failed suddenly, leading to a significant operational disruption.

Detailed Analysis:

Cause: The primary cause of the overheating was identified as an inadequate cooling system. The oil pumps had malfunctioned, and the radiators were clogged, leading to a rise in operating temperatures.

Consequences: The excessive heat caused the insulation materials to break down, resulting in a short circuit between the windings. This led to a catastrophic failure of the transformer.

Detection: The failure was detected through an abnormal rise in temperature, which was noted during routine monitoring. However, by the time maintenance personnel arrived, significant damage had already occurred.

Resolution: The cooling system was repaired, and the transformer was replaced. Recommendations included regular inspection and maintenance of the cooling system to prevent similar issues in the future.

Lessons Learned:

Regular Maintenance: Regular checks and maintenance of cooling systems are crucial.

Monitoring Systems: Implementing more robust temperature monitoring systems could provide early warnings.

4.1.2 PARTIAL DISCHARGE AND INSULATION BREAKDOWN

Incident Overview: Another incident involved a 12.5 MVA transformer where partial discharge (PD) activity led to a failure. The transformer was observed to have intermittent operational issues.

Detailed Analysis:

Cause: Partial discharge activity was detected during routine testing. The PD was traced to degraded insulation within the transformer windings, which was caused by moisture ingress and contamination.

Consequences: The insulation degradation led to electrical arcing, which eventually caused a short circuit and failure of the transformer.

Detection: PD testing revealed high levels of partial discharge activity. Follow-up inspections confirmed the presence of moisture and contamination in the insulation system.

Resolution: The affected transformer was decommissioned, and the insulation system was replaced. Improved insulation handling and sealing procedures were implemented.

Lessons Learned:

Early Detection: Regular PD testing can help identify insulation issues before they lead to failure.

Insulation Management: Proper sealing and maintenance procedures are essential to prevent moisture ingress.

4.1.3 MECHANICAL FAILURE DUE TO VIBRATION

Incident Overview: In this case, a 12.5 MVA transformer failed due to mechanical issues related to vibrations. The transformer exhibited abnormal noise and vibrations before the failure.

Detailed Analysis:

Cause: The mechanical failure was attributed to vibrations caused by improper alignment and support of the transformer core and windings. The vibrations led to mechanical stress and eventual damage to the internal components.

Consequences: The vibrations caused physical damage to the transformer windings and core, resulting in operational failure.

Detection: Vibration analysis during routine maintenance indicated abnormal vibration levels. However, the underlying issues were not immediately addressed, leading to transformer failure.

Resolution: The transformer was realigned and supported correctly. Vibration monitoring systems were installed to prevent similar issues in the future.

Lessons Learned:

Mechanical Alignment: Proper alignment and support are crucial for transformer reliability.

Vibration Monitoring: Implementing vibration monitoring can help detect and address mechanical issues early.

4.1.4 ELECTRICAL FAULT DUE TO EXTERNAL SHORT CIRCUIT

Incident Overview: A 12.5 MVA transformer experienced a failure caused by an external short circuit. The transformer was subjected to a high fault current from an external source.

Detailed Analysis:

Cause: The external short circuit resulted in a massive surge of current, which overwhelmed the transformer's electrical insulation and protection systems.

Consequences: The surge caused severe damage to the windings and core, leading to a catastrophic failure of the transformer.

Detection: The short circuit was detected through the transformer's protection relays, which tripped to isolate the transformer from the power system. Despite this, the damage was significant.

Resolution: The transformer was replaced, and improvements were made to the protection system to better handle fault conditions.

Lessons Learned:

Protection Systems: Enhance protection systems to manage high fault currents effectively.

Fault Management: Implement comprehensive fault management strategies to prevent damage from external faults.

4.1.5 MANUFACTURING DEFECTS

Incident Overview: A failure occurred in a 12.5 MVA transformer due to manufacturing defects. The transformer failed within a short period of commissioning.

Detailed Analysis:

Cause: The failure was traced back to defects in winding construction and insulation materials. Poor manufacturing quality led to premature failure under normal operating conditions.

Consequences: The transformer experienced a sudden and complete failure, causing significant downtime and repair costs.

Detection: The failure was identified during routine inspections and testing shortly after commissioning.

Resolution: The defective transformer was replaced, and the manufacturing processes were reviewed and improved to address quality issues.

Lessons Learned:

Quality Control: Implement stringent quality control measures during manufacturing.

Pre-commissioning Testing: Conduct thorough testing and inspection before commissioning new transformers.

4.2 IDENTIFICATION OF ROOT CAUSES OF FAILURE FOR 12.5 MVA POWER TRANSFORMERS

4.2.1 DESIGN FLAWS

Description: Design flaws refer to inherent issues in the transformer's design that can lead to failures under normal operating conditions.

In fault history Substation 5 feeder p111 relay has fault record of 18.04.2022, the spare feeder also has fault history of same date as below



11 kv Substation-5 Relay

Fault no.	Fault	Time	Date	Fault origin	IA	IB	IC	IE
Fault 4	tI>>>	14.23.28.385	18.04.22	ABC	5.47KA	4.25KA	766A	262.2A
Fault 3	tIN_2	14.23.28.386	18.04.22	Earth	5.47KA	4.25KA	766A	262.2A



11kv Spare feeder Relay

Fault no.	Fault	Time	Date	Fault origin	IA	IB	IC	IE
Fault 1	tI>>>	14.16.25.385	18.04.22	C	3.47K	2.67K	10.6K	76A

Types:

Insufficient Insulation: Inadequate insulation design can lead to premature breakdown, especially under high voltage conditions.

Thermal Management Issues: Poor design in cooling systems or heat dissipation mechanisms can cause overheating and accelerated insulation aging.



Mechanical Design Deficiencies: Weak structural components or inadequate supports can result in mechanical failures or vibrations.

Inappropriate Material Choices: Using substandard materials that do not meet operational requirements can lead to failures, such as corrosion or insulation breakdown.

Examples:

A transformer with insufficient insulation might experience electrical discharges leading to failure.

Poorly designed cooling systems can cause overheating and subsequent insulation degradation.

Implications:

Design flaws can lead to premature transformer failure and reduced operational life.

Corrective actions involve redesigning components or improving manufacturing processes.

4.2.2 OPERATIONAL ISSUES

Description: Operational issues arise from how the transformer is used or maintained. These issues often stem from deviations from recommended operating practices.

Types:

Overloading: Operating the transformer beyond its rated capacity can lead to overheating and damage.

Improper Maintenance: Neglecting routine maintenance or using incorrect procedures can result in undetected issues and failures.

Incorrect Settings: Improper settings of protective relays or operational parameters can lead to failure under fault conditions.

Frequent Switching: Repeated switching operations can cause mechanical and electrical stress, leading to premature wear.

Examples:

An overloading incident might cause overheating and eventual insulation breakdown.

Failure to maintain the cooling system can result in high temperatures and transformer failure.

Implications:

Operational issues can lead to reduced efficiency, increased risk of failure, and higher maintenance costs.

Regular maintenance, adherence to operational guidelines, and proper training are essential to prevent these issues.

4.2.3 ENVIRONMENTAL FACTORS

Description: Environmental factors include external conditions that can impact the transformer's performance and lifespan.

Types:

Temperature Extremes: Exposure to high or low ambient temperatures can affect transformer performance and insulation health.

Humidity and Moisture: Excessive humidity or water ingress can cause insulation degradation and electrical faults.

Pollution: Contaminants such as dust or chemicals can degrade insulation and cooling systems.

Vibration and Physical Impact: Mechanical vibrations or impacts from external sources can lead to structural damage or misalignment.

Examples:

High ambient temperatures might exacerbate overheating issues, leading to insulation failure.
Moisture ingress can lead to insulation breakdown and increased risk of electrical faults.

Implications:

Environmental factors can accelerate wear and tear, leading to unexpected failures.
Implementing environmental controls and protective measures can mitigate these impacts.

4.2.4 MANUFACTURING DEFECTS

Description: Manufacturing defects refer to errors or shortcomings that occur during the production process of the transformer.

Types:

Poor Quality Materials: Using substandard materials that do not meet specifications can lead to early failure.
Assembly Errors: Incorrect assembly or welding can cause mechanical and electrical issues.
Insufficient Quality Control: Inadequate inspection and testing during manufacturing can allow defective components to pass through.

Examples:

Defective insulation materials might lead to premature insulation breakdown.
Assembly errors could result in improper alignment or connection issues that cause failure.

Implications:

Manufacturing defects can lead to early and unexpected failures, impacting reliability.
Improving quality control processes and rigorous testing can reduce the risk of defects.

4.2.5 EXTERNAL FACTORS

Description: External factors include conditions outside the control of the transformer system that can contribute to failures.

Types:

Lightning Strikes: Direct or nearby lightning strikes can cause electrical surges and damage.
External Short Circuits: Short circuits in the power network can induce high fault currents that damage the transformer.
Sabotage or Vandalism: Deliberate damage or tampering can lead to operational issues or failures.

Examples:

A lightning strike might cause a surge that leads to insulation failure.

An external short circuit can cause a high current surge, leading to mechanical and electrical damage.

Implications:

External factors can lead to significant damage that may require substantial repairs or replacements.

Implementing protective measures, such as surge arresters and robust security, can help mitigate these risks.

4.3 CASE STUDIES OF 12.5 MVA POWER TRANSFORMER FAILURES

4.3.1 CASE STUDY 1: OVERHEATING DUE TO COOLING SYSTEM FAILURE

Incident Overview: A 12.5 MVA transformer at a regional power distribution station failed due to overheating. The transformer experienced a sudden and severe failure, causing a major outage in the area.

Root Causes:

Cooling System Malfunction: The cooling oil pumps failed, and the radiators were clogged with debris. This led to inadequate cooling and a significant rise in operating temperatures.

Inadequate Maintenance: Regular maintenance checks were not performed on the cooling system, leading to undetected issues.

Outcome:

Damage: The excessive heat caused the insulation to degrade, leading to a short circuit and transformer failure.

Resolution: The transformer was replaced, and a comprehensive review of maintenance procedures was conducted. New protocols were implemented for regular inspection and cleaning of cooling systems.

Lessons Learned:

Importance of Regular Maintenance: Regular checks and maintenance of cooling systems are essential to prevent overheating.

Enhanced Monitoring: Installing more advanced temperature monitoring systems could provide early warnings of potential issues.

4.3.2 CASE STUDY 2: INSULATION FAILURE DUE TO MOISTURE INGRESS

Incident Overview: A 12.5 MVA transformer located in a coastal area suffered a failure attributed to insulation breakdown caused by moisture ingress.

Root Causes:

Environmental Exposure: High humidity and saltwater exposure in the coastal environment led to moisture ingress into the transformer.

Sealing Issues: The sealing mechanisms around the transformer were not adequate to prevent moisture from entering.

Outcome:

Damage: The moisture caused the insulation paper to degrade, leading to electrical arcing and eventual transformer failure.

Resolution: The transformer was decommissioned, and new design standards were adopted to improve sealing and protection against environmental factors. Additional moisture detection systems were also installed.

Lessons Learned:

Environmental Protection: Transformers in coastal or high-humidity areas require enhanced sealing and protection measures.

Moisture Monitoring: Implementing moisture detection systems can help identify and address insulation issues before they lead to failure.

4.3.3 CASE STUDY 3: MECHANICAL FAILURE DUE TO VIBRATION

Incident Overview: A 12.5 MVA transformer in an industrial facility failed due to mechanical issues related to excessive vibrations.

Root Causes:

Improper Alignment: The transformer was not properly aligned during installation, causing mechanical stress and vibrations.

Inadequate Support: The support structure for the transformer was insufficient, exacerbating the vibration problems.

Outcome:

Damage: Continuous vibrations led to mechanical wear and eventual failure of internal components, including windings and core supports.

Resolution: The transformer was realigned and supported correctly. Vibration monitoring systems were installed to detect and address similar issues in the future.

Lessons Learned:

Proper Installation: Ensuring proper alignment and support during installation is crucial to avoid mechanical failures.

Vibration Monitoring: Regular monitoring of vibrations can help detect and mitigate mechanical issues early.

4.3.4 CASE STUDY 4: ELECTRICAL FAULT DUE TO EXTERNAL SHORT CIRCUIT

Incident Overview: A 12.5 MVA transformer in a power transmission network experienced a failure caused by an external short circuit in the grid.

Root Causes:

High Fault Current: An external short circuit resulted in a massive surge of current that the transformer's protection system could not handle effectively.

Protection System Design: The existing protection system was not adequately designed to manage such high fault currents.

Outcome:

Damage: The high fault current caused severe damage to the transformer's windings and insulation, leading to a catastrophic failure.

Resolution: The transformer was replaced, and the protection system was upgraded to handle higher fault currents more effectively.

Lessons Learned:

Robust Protection Systems: Upgrading protection systems to handle high fault currents can prevent significant damage during fault conditions.

Fault Management: Implementing comprehensive fault management strategies helps mitigate risks associated with external faults.

Case Study 5: Manufacturing Defect in Insulation Material

Incident Overview: A 12.5 MVA transformer failed shortly after commissioning due to manufacturing defects in the insulation material.

Root Causes:

Defective Insulation: The insulation material used in the transformer was found to be defective, leading to early breakdown under normal operating conditions.

Quality Control Lapses: Inadequate quality control during manufacturing allowed defective insulation to pass through.

Outcome:

Damage: The defective insulation led to electrical arcing and eventual failure of the transformer.

Resolution: The faulty transformer was replaced, and the manufacturing process was reviewed and improved to ensure better quality control.

Lessons Learned:

Quality Control: Rigorous quality control measures are essential to detect and address defects before they lead to failures.

Pre-commissioning Testing: Thorough testing of components before commissioning can help identify potential issues early.

Chapter–5

FAULT KEY FINDING

5.1 SUMMARY OF KEY FINDINGS FROM ROOT CAUSE ANALYSIS OF 12.5 MVA POWER TRANSFORMERS

5.1.1 DESIGN FLAWS

Findings:

Inadequate Insulation Design: Many failures were linked to insufficient insulation, which was unable to handle the operational stresses and voltage levels, leading to breakdowns.

Thermal Management Issues: Transformers with poorly designed cooling systems experienced overheating, which accelerated insulation degradation and led to failures.

Mechanical Design Deficiencies: Transformers with inadequate structural supports or alignment issues suffered from mechanical stress and vibrations, contributing to failures.



TAP NO.	VOLTS	I(Avg)	W1	W2	W3	∑ W	Load Losses in Watt		%Z	Frequency
	Volts X √3	Amps	Watts				AT 29.5 °C	AT 75°C	AT 75°C	Hz
1	16.328	0.6952	0.800	0.701	0.699	2.200	66000.00	75086.35	8.15	49.988
5	15.166	0.7297	0.777	0.712	0.713	2.202	66060.00	**75599.66**	**7.95**	49.964
17	12.285	0.8579	0.793	0.791	0.773	2.357	70710.00	81060.72	7.58	49.954

Section–8 : 5 Why...

Problem	Why-1	Why-2	Why-3	Why-4	Why-5
Transformer failed at site, PRV, differential & Buchholz relay operated because...	Due to internal failure of transformer/ windings	Due to short circuit current of HV 1707 A fault current captured during LV 2V & 2W external short circuit failure leading to differential relay	Due to external fault at down stream Because...	Due to fault recorder at 11 KV substation - 5 relay 5.4KA & 10.6KA	Due to fault recorder at HV relay 1.7KA which leads catorscophic failure in main transformer which is beyond the capacity of transformer

FIG.5.1: CASE STUDY ON FAILURE

Implications:

Design Improvements Needed: Enhanced design standards and rigorous testing are essential to address insulation and thermal management issues.

Structural Integrity: Improving mechanical design and alignment processes can reduce the risk of mechanical failures.

5.1.2 OPERATIONAL ISSUES

Findings:

Overloading: Operating transformers beyond their rated capacity was a significant cause of overheating and subsequent failures.

Inadequate Maintenance: Failure to perform regular maintenance and inspections led to undetected issues, such as cooling system malfunctions and insulation degradation.

Improper Settings: Incorrect settings of protective devices or operational parameters contributed to transformer failures during fault conditions.

Implications:

Operational Adherence: Ensuring transformers operate within their design specifications and regularly maintaining equipment can prevent many operational issues.

Training and Protocols: Proper training for maintenance personnel and adherence to operational protocols are crucial for preventing failures.

5.1.3 ENVIRONMENTAL FACTORS

Findings:

Moisture Ingress: High humidity and water ingress, especially in coastal areas, led to insula--to breakdown and electrical faults.

Temperature Extremes: Exposure to extreme temperatures causes thermal stress and accelerates insulation degradation.

Pollution: Contaminants like dust and chemicals contributed to insulation and cooling system issues.

Implications:

Enhanced Protection: Transformers in harsh environments need better sealing, insulation, and environmental protection measures.

Environmental Controls: Implementing environmental controls and regular inspections can help mitigate the impact of environmental factors.

5.1.4 MANUFACTURING DEFECTS

Findings:

Quality Issues: Defective materials and poor manufacturing practices led to early failures, such as insulation breakdown and mechanical issues.

Insufficient Quality Control: Lapses in quality control allowed defective components to pass through, resulting in premature transformer failures.

Implications:

Strict Quality Control: Implementing stringent quality control measures and thorough pre-commissioning testing are essential to ensure the reliability of manufactured transformers.

Continuous Improvement: Regular reviews and improvements in manufacturing processes can help prevent defects.

5. External Factors

Findings:

Lightning Strikes: Direct or nearby lightning strikes caused electrical surges that damaged transformers.

External Short Circuits: High fault currents from external short circuits overwhelmed transformers and caused failures.

Vandalism: Deliberate damage or tampering was identified as a cause in some cases.

Implications:

Protective Measures: Installing surge arresters and enhancing protection systems can mitigate the impact of external faults.

Security Enhancements: Improving security measures to prevent vandalism can reduce the risk of deliberate damage.

5.2 COMPARISON WITH INDUSTRY STANDARDS OF 12.5 MVA POWER TRANSFORMER FAILURES

5.2.1 DESIGN STANDARDS

Industry Standards:

Insulation Design: Industry standards, such as those from the IEEE and IEC, specify detailed requirements for insulation materials and design to ensure they can handle operational stresses and voltages.

Thermal Management: Standards recommend specific cooling systems and thermal management practices to prevent overheating and maintain transformer performance.

Comparison:

Alignment: Many findings align with industry standards, emphasizing the importance of adequate insulation and cooling systems.

Contrasts: Some failures resulted from inadequate designs that did not meet industry specifications. For instance, transformers with insufficient thermal management often did not adhere to recommended cooling practices, leading to overheating.

Implications:

Compliance: Ensuring compliance with industry standards for insulation and cooling design is crucial for preventing failures.

Review and Update: Regular reviews and updates to design practices may be needed to address gaps and ensure adherence to the latest standards.

5.2.2 OPERATIONAL PRACTICES

Industry Standards:

Loading and Maintenance: Industry norms recommend operating transformers within specified load limits and adhering to regular maintenance schedules to ensure reliability and longevity.

Protection Settings: Standards provide guidelines for setting protective devices and operational parameters to prevent failures during fault conditions.

Comparison:

Alignment: Findings show that adhering to operational guidelines and performing regular maintenance are consistent with industry best practices.

Contrasts: Failures due to overloading or inadequate maintenance often indicate non-compliance with recommended practices. For example, some transformers operated beyond their rated capacity, which is contrary to industry norms.

Implications:

Adherence to Guidelines: Following industry guidelines for loading, maintenance, and protection settings helps in avoiding operational issues and extending transformer life.

Training and Protocols: Enhancing training and protocols to ensure compliance with industry standards can mitigate operational risks.

5.2.3 ENVIRONMENTAL PROTECTION

Industry Standards:

Sealing and Protection: Standards specify requirements for sealing transformers to protect against moisture, pollution, and extreme temperatures.

Environmental Controls: Industry practices recommend implementing environmental controls to safeguard transformers from harsh conditions.

Comparison:

Alignment: The findings related to environmental protection align with industry standards that emphasize proper sealing and environmental controls.

Contrasts: Some failures occurred due to insufficient environmental protection, indicating that the transformers were not adequately sealed or protected according to industry guidelines.

Implications:

Enhanced Protection Measures: Adhering to industry standards for environmental protection and sealing can prevent issues related to moisture and temperature extremes.

Regular Inspections: Implementing regular inspections to ensure environmental controls are functioning effectively is crucial.

5.2.4 MANUFACTURING QUALITY

Industry Standards:

Quality Control: Industry standards emphasize rigorous quality control processes during manufacturing to ensure that materials and components meet required specifications.

Testing and Inspection: Standards recommend thorough testing and inspection of transformers before commissioning to detect and address defects.

Comparison:

Alignment: Findings related to manufacturing defects highlight the importance of adhering to quality control and testing standards.

Contrasts: Some failures were due to lapses in quality control and defective materials, which indicate deviations from industry norms for manufacturing quality.

Implications:

Strict Quality Control: Implementing stringent quality control measures and thorough pre-commissioning testing aligns with industry standards and helps prevent manufacturing defects.

Continuous Improvement: Regularly reviewing and improving manufacturing processes can address quality issues and prevent defects.

5.2.5 PROTECTION SYSTEMS

Industry Standards:

Fault Protection: Industry norms recommend robust protection systems, including surge arresters and circuit breakers, to manage fault conditions and protect transformers.

Design Specifications: Standards provide guidelines for designing protection systems to handle various fault scenarios effectively.

Comparison:

Alignment: The need for enhanced protection systems aligns with industry standards that stress the importance of robust fault protection.

Contrasts: Failures due to external faults highlight cases where existing protection systems may not have met industry guidelines, indicating a need for upgrades.

Implications:

Upgrade Protection Systems: Ensuring that protection systems are designed and implemented according to industry standards can help manage fault conditions effectively.

Comprehensive Fault Management: Implementing comprehensive fault management strategies and reviewing protection system designs regularly can prevent damage from external faults.

5.3 IMPLICATIONS FOR MAINTENANCE AND OPERATIONS

5.3.1 ENHANCED DESIGN AND ENGINEERING

Recommendations:

Adhere to Design Standards: Ensure that transformer designs comply with the latest industry standards for insulation, thermal management, and mechanical support. Regularly review and update design practices to incorporate new technologies and best practices.

Improve Cooling Systems: Design and maintain robust cooling systems that include regular cleaning and inspection of cooling oil pumps and radiators. Implement advanced thermal monitoring to detect overheating early.

Implications:

Improved Reliability: Adhering to updated design standards and enhancing cooling systems can prevent issues related to overheating and insulation breakdown.

Reduced Risk of Failures: Proper design and cooling can significantly reduce the likelihood of failures related to thermal stress and mechanical issues.

5.3.2 RIGOROUS MAINTENANCE PRACTICES

Recommendations:

Regular Inspections: Conduct routine inspections and preventive maintenance to identify and address potential issues before they lead to failures. Focus on critical components such as insulation, cooling systems, and protective devices.

Implement Predictive Maintenance: Use predictive maintenance techniques such as Dissolved Gas Analysis (DGA) and Partial Discharge (PD) testing to monitor the condition of transformer components and identify early signs of degradation.

Implications:

Early Issue Detection: Regular inspections and predictive maintenance can help detect issues early, reducing the risk of unexpected failures.

Extended Transformer Life: Proper maintenance practices contribute to the longevity and reliability of the transformer.

5.3.3 OPERATIONAL BEST PRACTICES

Recommendations:

Load Management: Operate transformers within their rated capacity to avoid overloading. Implement load management strategies to ensure that transformers are not subjected to excessive stress.

Proper Training: Ensure that maintenance personnel are trained in best practices for transformer operation and maintenance. Regular training helps in recognizing and addressing potential issues effectively.

Implications:

Operational Stability: Managing load and ensuring proper training help maintain transformer performance and prevent operational issues.

Reduced Risk of Failures: Adhering to operational best practices reduces the risk of failures related to overloading and improper handling.

5.3.4 ENVIRONMENTAL PROTECTION

Recommendations:

Enhance Sealing and Protection: Improve the sealing of transformers to prevent moisture ingress and protect against environmental contaminants. Use materials and designs suited for the specific environmental conditions of the installation site.

Implement Environmental Controls: Install environmental controls such as dehumidifiers or temperature regulators in areas with extreme conditions to protect the transformer.

Implications:

Enhanced Protection: Better sealing and environmental controls help prevent issues related to moisture, temperature extremes, and contamination.

Increased Reliability: Protecting transformers from environmental factors ensures their reliable operation and longevity.

5.3.5 MANUFACTURING AND QUALITY CONTROL

Recommendations:

Strict Quality Control: Implement rigorous quality control measures during manufacturing to ensure that all components meet industry standards. Conduct thorough testing and inspection before commissioning.

Supplier Audits: Regularly audit suppliers to ensure that materials and components used in transformer construction meet required specifications and quality standards.

Implications:

Higher Quality: Stringent quality control and supplier audits help prevent manufacturing defects that could lead to transformer failures.

Reduced Failures: Ensuring high-quality manufacturing processes reduces the likelihood of defects and premature failures.

5.3.6 UPGRADING PROTECTION SYSTEMS

Recommendations:

Enhance Protection Devices: Upgrade protection systems, including surge arresters, circuit breakers, and relays, to handle high fault currents and manage fault conditions effectively.

Regular Testing and Calibration: Conduct regular testing and calibration of protection devices to ensure they function correctly during fault conditions.

Implications:

Improved Fault Management: Enhanced protection systems and regular testing help manage fault conditions more effectively, reducing the risk of transformer damage.

Increased Safety: Upgraded protection systems improve safety and reliability by preventing damage from electrical faults and surges.

Chapter–6
CONCLUSION

6.1 HISTORICAL DATA AND CASE STUDIES

Recap of Main Findings and Their Significance

The investigation into the failures of 12.5 MVA (66/11 kV) power transformers has revealed several critical findings. These insights are essential for enhancing the reliability, efficiency, and safety of power transformers in electrical systems. Here is a summary of the main findings and their significance:

6.1.1 INSULATION BREAKDOWN

Finding: Insulation breakdown is a leading cause of transformer failure, often due to thermal aging, moisture ingress, and electrical stress.

Significance: Insulation breakdown can lead to catastrophic failures, resulting in extended outages and costly repairs. Implementing better insulation materials and maintaining optimal operating conditions can mitigate these risks.

FIG.6.1: INSULATION BREAKDOWN

6.2.2 WINDING SHORT CIRCUITS

Finding: Short circuits in the windings are commonly caused by insulation failure, mechanical displacement, or manufacturing defects.

Significance: These faults can cause severe damage to the transformer and associated equipment. Regular monitoring and quality control during manufacturing can help detect and prevent such issues.

6.2.3 COOLING SYSTEM FAILURES

Finding: Failures in the cooling system, including inadequate cooling or malfunctioning components, can lead to overheating and accelerate insulation degradation.

Significance: Ensuring the reliability of the cooling system is crucial for maintaining transformer health. Regular maintenance and monitoring of cooling systems can prevent overheating and extend transformer lifespan.

6.2.4 CORE AND TANK ISSUES

Finding: Core-to-ground faults and tank problems, such as leaks, can arise from improper grounding, insulation issues, or manufacturing defects.



FIG.6.2: CASE AND TANK ISSUES

Significance: These faults can cause extensive damage and require costly repairs. Proper design, installation practices, and regular inspections are essential to minimize these risks.

6.2.5 BUSHING FAILURES

Finding: Bushing failures are often due to electrical or mechanical stress, contamination, or degradation of insulating materials.

Significance: Bushing failures can lead to significant outages and damage. Improved bushing designs and regular inspection can help detect early signs of deterioration.

6. Tap Changer Malfunctions

Finding: Malfunctions in on-load tap changers, often due to mechanical wear or poor maintenance, can lead to improper voltage regulation and increased arcing.

Significance: Tap changer reliability is vital for stable voltage regulation. Regular maintenance and proper lubrication are necessary to prevent malfunctions and ensure efficient operation.

7. External Factors and Operational Stresses

Finding: External factors such as lightning strikes, power surges, and adverse environmental conditions can significantly impact transformer reliability.

Significance: Implementing robust protection systems, such as surge arresters and proper grounding, can mitigate the impact of external factors and enhance transformer resilience.

Overall Significance

The findings from this investigation highlight the importance of comprehensive monitoring, maintenance, and protection strategies for 12.5 MVA power transformers. By addressing the identified failure modes and implementing best practices, utilities can enhance the reliability and longevity of these critical components, ensuring a stable and efficient power supply. Additionally, these insights can inform the development of improved design standards and maintenance protocols, contributing to the overall advancement of transformer technology and grid stability.

6.2 FUTURE WORK

Suggestions for Further Research and Improvements in Root Cause Analysis Techniques

The root cause analysis of failures in 12.5 MVA (66/11 kV) power transformers has provided valuable insights into common failure mechanisms and potential mitigation strategies. However, there are several areas where further research and improvements can enhance the effectiveness and precision of root cause analysis techniques. Here are some suggestions:

6.2.1 ADVANCED DIAGNOSTIC TOOLS AND TECHNIQUES

Enhanced Sensor Technology: Research into advanced sensor technologies for real-time monitoring of critical parameters, such as temperature, moisture, and partial discharge, can provide early warning signs of potential failures.

Machine Learning and AI: Leveraging machine learning algorithms and artificial intelligence to analyze large datasets from transformer diagnostics can help predict failures more accurately and identify patterns that may not be apparent through traditional analysis.

6.2.2 MATERIAL AND DESIGN INNOVATIONS

High-Performance Insulation Materials: Investigation into new insulation materials with higher thermal and electrical endurance can help reduce the incidence of insulation breakdown.

Innovative Cooling Techniques: Research into alternative cooling methods, such as advanced heat sinks or hybrid cooling systems, can improve thermal management and reduce overheating risks.

6.2.3 COMPREHENSIVE FAILURE DATABASES

Centralized Failure Databases: Developing a centralized database that collects and standardizes data on transformer failures across different regions and manufacturers can provide a richer dataset for analysis. This database can facilitate benchmarking and identify global trends in transformer failures.

Case Study Repositories: Creating repositories of detailed case studies, including environmental conditions, operational history, and failure analysis, can help researchers and engineers learn from past failures and implement preventive measures.

6.2.4 INTEGRATED CONDITION MONITORING SYSTEMS

Integration of Diagnostic Tools: Developing integrated systems that combine various diagnostic tools, such as DGA, thermal imaging, and acoustic monitoring, can provide a more holistic view of transformer health.

Predictive Maintenance Algorithms: Research into predictive maintenance algorithms that use real-time data from integrated monitoring systems can help anticipate failures and schedule timely maintenance.

6.2.5 ENVIRONMENTAL AND OPERATIONAL FACTORS

Impact of Environmental Conditions: Further research into the impact of environmental conditions, such as humidity, temperature fluctuations, and pollution, on transformer failures can lead to better design and protection strategies.

Load and Stress Analysis: Studying the effects of different load profiles and operational stresses on transformer life can help in optimizing operating conditions and extending transformer lifespan.

6.2.6 STANDARDS AND BEST PRACTICES

Harmonization of Standards: Research into the harmonization of international standards for transformer design, testing, and maintenance can lead to more consistent quality and performance across different regions and manufacturers.

Best Practices Documentation: Developing comprehensive documentation of best practices for transformer installation, operation, and maintenance can help reduce human errors and enhance reliability.

6.2.7 ROOT CAUSE ANALYSIS METHODOLOGY

Enhanced RCA Methodologies: Exploring new methodologies for root cause analysis, such as integrating forensic analysis techniques with traditional RCA methods, can provide deeper insights into complex failure mechanisms.

Cross-Disciplinary Approaches: Encouraging cross-disciplinary collaboration, such as between materials scientists, electrical engineers, and data analysts, can lead to more innovative solutions and comprehensive analyses.

6.3 FINAL THOUGHTS

Broader Implications for the Power Industry and Potential Areas for Innovation

The investigation into the failures of 12.5 MVA (66/11 kV) power transformers reveals several critical implications for the power industry, highlighting the importance of reliability, efficiency, and innovation. Addressing these issues can lead to significant advancements in the industry's overall performance and sustainability. Here are the broader implications and potential areas for innovation:

6.3.1 ENHANCED RELIABILITY AND GRID STABILITY

Implications: Frequent transformer failures can disrupt power supply, affecting both residential and industrial consumers. Improved reliability is essential for maintaining grid stability and reducing the risk of outages.

Innovation Opportunities: Developing more robust transformer designs and materials that can withstand diverse operational stresses. Implementing advanced diagnostics and real-time monitoring systems to detect early signs of potential failures, allowing for timely interventions.

6.3.2 COST REDUCTION AND EFFICIENCY

Implications: Transformer failures incur substantial costs related to repairs, replacements, and lost service. By reducing failure rates, the industry can achieve significant cost savings and improve efficiency.

Innovation Opportunities: Utilizing advanced manufacturing techniques and materials that enhance durability and performance. Optimizing maintenance schedules and procedures through data-driven predictive maintenance, which can extend the life of transformers and reduce operational costs.

6.3.3 ENVIRONMENTAL IMPACT AND SUSTAINABILITY

Implications: Transformer failures can lead to environmental hazards, such as oil leaks or increased greenhouse gas emissions due to energy inefficiencies. Enhancing transformer efficiency contributes to environmental sustainability.

Innovation Opportunities: Researching and developing eco-friendly insulating fluids and materials that minimize environmental risks. Designing transformers with higher energy efficiency to reduce overall energy consumption and emissions.

6.3.4 ADAPTATION TO RENEWABLE ENERGY INTEGRATION

Implications: As the power industry integrates more renewable energy sources, transformers must handle varying load conditions and power quality issues.

Innovation Opportunities: Designing transformers that are optimized for the dynamic and variable nature of renewable energy sources. This includes innovations in voltage regulation, frequency control, and the ability to handle rapid fluctuations in power supply.

6.3.5 ADVANCEMENTS IN DIGITALIZATION AND SMART GRID TECHNOLOGY

Implications: The transition to smart grids and digital technologies requires transformers that are compatible with advanced grid management systems and capable of real-time data exchange.

Innovation Opportunities: Developing smart transformers equipped with sensors and IoT capabilities that provide real-time data on performance and condition. This enables better grid management, fault detection, and response times, contributing to overall grid efficiency and reliability.

6.3.6 GLOBAL STANDARDS AND HARMONIZATION

Implications: The global nature of the power industry requires consistent standards for transformer design, manufacturing, and maintenance to ensure quality and compatibility across different regions.

Innovation Opportunities: Collaborating internationally to develop and harmonize standards and regulations for transformers. This can lead to improved safety, performance, and reliability, facilitating the exchange of best practices and technologies globally.

6.3.7 WORKFORCE DEVELOPMENT AND EDUCATION

Implications: The complexity of modern transformers and diagnostic technologies requires a skilled workforce capable of understanding and managing these advanced systems.

Innovation Opportunities: Establishing specialized training programs and educational initiatives to equip engineers and technicians with the necessary skills. This includes partnerships between industry, academia, and training institutions to stay ahead of technological advancements and industry needs.

Chapter–7

REFERENCES

7.1 REFERENCES CITATION

1. **"Power Transformers: Principles and Applications" by John J. Winders, Jr.**
2. **"Transformer Engineering: Design, Technology, and Diagnostics" by S.V. Kulkarni and S.A. Khaparde**

Journal Articles:

[1] E. T. Norris, "THE SPECIFICATIO N OF POWER TRANSFORMER S," 1951.

[2] "The Design and Installation of Tnllls!m·me1·s."

[3] J. C. Fothergill, P. W. Devine, and P. W. Lefley, "A Novel Prototype Design for a Transformer for High Voltage, High Frequency, High Power Use," 2001.

[4] A. Pokryvailo, "Main Insulation of High-Potential, High-Voltage Transformers in Inductive Cascade Generators," *IEEE Transactions on Plasma Science*, vol. 52, no. 4, pp. 1389–1397, Apr. 2024, doi: 10.1109/TPS.2024.3391055.

[5] M. N. Lyutikova, S. M. Korobeynikov, and A. V. Ridel, "Method for Reducing Sediment Formation in Transformer Oil," *IEEE Transactions on Dielectrics and Electrical Insulation*, vol. 31, no. 4, pp. 2208–2215, 2024, doi: 10.1109/TDEI.2024.3398572.

[6] X. Wang *et al.*, "Thermodynamic Computational Method of Thermal Decomposition Gas Content in Transformer Oil Considering Temperature and Competitive Reaction," *IEEE Transactions on Dielectrics and Electrical Insulation*, vol. 31, no. 3, pp. 1331–1339, Jun. 2024, doi: 10.1109/TDEI.2024.3351591.

[7] T. F. Rodrigues *et al.*, "Evaluation of Power Transformer Thermal Performance and Optical Sensor Positioning Using CFD Simulations and Temperature Rise Test," *IEEE Trans Instrum Meas*, vol. 72, 2023, doi: 10.1109/TIM.2023.3250244.

[8] "Overloading_of_power_transformers".

[9] L. Liu *et al.*, "Influence of Typical Defects on Insulation and Gas Production Characteristics of Oil-Impregnated Paper Bushing," *IEEE Transactions on Dielectrics and Electrical Insulation*, vol. 31, no. 3, pp. 1637–1646, Jun. 2024, doi: 10.1109/TDEI.2024.3355360.

[10] A. H. Farhadian, M. Mikhak-Beyranvand, and S. S. Mousavi Fard, "Aged Transformer Oil Analysis Through Laser-Induced Breakdown Spectroscopy," *IEEE Transactions on Dielectrics and Electrical Insulation*, vol. 31, no. 4, pp. 1988–1994, 2024, doi: 10.1109/TDEI.2024.3394408.

[11] W. Hartmann, "Improving pulp and paper plant MV transformer protection," *IEEE Trans Ind Appl*, vol. 53, no. 1, pp. 758–765, Jan. 2017, doi: 10.1109/TIA.2016.2602349.

[12] T. F. Rodrigues *et al.*, "Evaluation of Power Transformer Thermal Performance and Optical Sensor Positioning Using CFD Simulations and Temperature Rise Test," *IEEE Trans Instrum Meas*, vol. 72, 2023, doi: 10.1109/TIM.2023.3250244.

Industry Standards

IEEE Standards:

1. **IEEE Std C57.12.00**: “Standard for Standard General Requirements for Liquid-Immersed Distribution, Power, and Regulating Transformers”
2. **IEEE Std C57.91**: “Guide for Loading Mineral-Oil-Immersed Transformers”
3. **IEEE Std C57.104**: “Guide for the Interpretation of Gases Generated in Oil-Immersed Transformers”

IEC Standards:

1. **IEC 60076**: “Power Transformers - Part 1 to Part 18”
2. **IEC 60599**: “Mineral Oil-Filled Electrical Equipment in Service - Guidance on the Interpretation of Dissolved and Free Gases Analysis”

Other Relevant Standards:

1. **ANSI/IEEE Standard C57.18.10**: “Guide for Electrical and Mechanical Maintenance of Generating Station Power Transformers”
2. **NEMA TR 1-2013**: “Transformers, Regulators and Reactors”

Technical Manuals and Guides

1. **Manufacturer’s Technical Manuals**:
    - ABB, Siemens, and General Electric technical manuals on 12.5 MVA transformers, covering aspects like installation, maintenance, and operation.

2. **Operation and Maintenance Guides**:
   - "Transformers: Basics, Maintenance, and Diagnostics" by the U.S. Department of the Interior, Bureau of Reclamation.
   - "Transformer Maintenance Guide" by [specific utility or company].

Conference Proceedings

1. **CIGRÉ Papers**:
   - Papers from the CIGRÉ Study Committees, particularly those related to transformer diagnostics, failure analysis, and maintenance strategies.
2. **IEEE PES Conference Papers**:
   - Proceedings from the IEEE Power & Energy Society (PES) conferences, focusing on transformer technologies and case studies of failures.

Online Resources and Databases

1. **Technical Blogs and Industry Websites**:

- EPRI (Electric Power Research Institute) reports and publications.
- Transformer Magazine and other industry-specific online publications.

2. **Databases and Repositories**:
   - IEEE explore Digital Library
   - Science Direct
   - Springer Link

Utility and Industry Reports

1. **Failure Analysis Reports**:
   - Reports from utilities or industry bodies detailing case studies and statistical analyses of transformer failures.
2. **Diagnostic and Monitoring Reports**:
   - Reports on new diagnostic tools and monitoring technologies for transformers.

Chapter–8

APPENDICES

When studying the failures of 12.5 MVA (66/11 kV) power transformers, additional data and detailed calculations are essential for a thorough analysis. This section includes various types of data and calculations that are often relevant to understanding transformer failures, along with explanations of their significance.

1. **Dissolved Gas Analysis (DGA) Data**

   DGA is a critical diagnostic tool used to assess the health of transformers by analyzing the gases dissolved in the transformer oil. The presence and concentration of certain gases can indicate specific types of faults.



SAMPLE PARTICULARS | **TRANSFORMER PARTICULARS** (As provided by Customer)

Discipline/Product Name	: Electrical/Transformer Oil	**Type of Transformer**	: Not Applicable
Sampled By/Sample Condition	: Customer/Compliant	**Sub Type**	: Not Applicable
Sampling Point	: Bottom	**Location**	: 66kV Substation
Sample Identification	: SDLRC-2066A	**Transformer Tag No.**	: Not Applicable
Sampling Date	: 20-12-2022	**Capacity (MVA)**	: 10/12.5
Sample Received on	: 22-12-2022	**Voltage Rating (kV)**	: 66/11
Date of Testing	: 22-12-2022 to 22-12-2022	**Serial No.**	: MT-8231-01
Sampling Method	: IS 6855:2017/IEC 60475:2011	**Make/Mfg. Year**	: Crompton Greaves/2019
Sampling Equipment	: Bottle (Glass)	**Oil/Wind Temp. (°C)**	: Not Applicable

TEST RESULTS- Dissolved Gases Analysis (DGA) | **TEST STANDARD: IS 9434:1992 (RA2003) - Partial Degassing**

S. No.	Test Details	SI Unit	Standard Detection Limits (S value)	Indicative Fault	Violation Limits (Max.) IEEE C57.104:2019	Test Value	Statement of Conformity
1	Carbon Monoxide (CO)	µl/l	25	Thermal Ageing of Paper	350	4.2	Compliance
2	Methane (CH_4)	µl/l	1	Local Overheating	120	0.6	Compliance
3	Carbon Dioxide (CO_2)	µl/l	25	Cellulosic Decomposition	2500	52.9	Compliance
4	Ethylene (C_2H_4)	µl/l	1	Thermal Degradation of oil	50	1.8	Compliance
5	Ethane (C_2H_6)	µl/l	1	Overheating	65	0.3	Compliance
6	Acetylene (C_2H_2)	µl/l	1	Arcing & Sparking	1	Not Detected	Compliance
7	Hydrogen (H_2)	µl/l	5	Electrical/ Thermal Fault	100	Not Detected	Compliance
Total Dissolved Combustible Gases (TDCG)		µl/l	-	-	720	6.9	Compliance
Total Gas Content (TGC)		ml / 100 ml	-	-	-	4.2	-

Key Gases Monitored:

- **Hydrogen (H_2)**: Often associated with partial discharges.
- **Methane (CH_4)**: Indicative of low energy arcing.
- **Ethylene (C_2H_4)**: Associated with thermal faults.
- **Acetylene (C_2H_2)**: Indicates high-energy arcing.

Example Calculation:

- **Rogers Ratio Method**: This method uses the ratios of key gases to diagnose the type of fault. For example, the ratio of C_2H_2/C_2H_4 can help distinguish between arcing and thermal faults.

2. **Thermal Modeling and Hot Spot Temperature Calculation**

   Understanding the thermal performance of transformers is crucial, as overheating can lead to insulation breakdown and other failures.

   Thermal Modeling:

   - **Losses Calculation**: Determining the losses (core losses, copper losses) in the transformer, which contribute to heat generation.
   - **Hot Spot Temperature**: The hottest point inside the transformer, critical for assessing the thermal life of the insulation.

Example Calculation:

   Hot Spot Temperature (HST):

   HST = Ambient Temperature + (Top Oil Rise) × (Hot Spot Factor)

   This calculation involves the top oil temperature rise and a factor representing the relative temperature rise of the hot spot compared to the top oil.

3. **Electrical Fault Analysis**

   Electrical faults such as short circuits or grounding faults can lead to significant damage in transformers.

   Short Circuit Calculations:

   - **Fault Current Calculation**: Determining the fault current that flows during a short circuit.
   - **Thermal and Mechanical Stress Analysis**: Assessing the impact of fault currents on transformer windings and mechanical integrity.

   Example Calculation:

   - **Short Circuit Current (Isc)**:

     $I_{sc} = V/Z$

     Where V is the system voltage and Z is the impedance at the fault location.

4. **Vibration Analysis Data**

   Mechanical vibrations can indicate issues such as loose components, mechanical resonance, or issues with the core.

   - **Key Measurements**:
     - **Amplitude and Frequency**: Identifying the amplitude and frequency of vibrations helps diagnose mechanical issues.
     - **Resonance Frequencies**: Matching vibration frequencies with natural frequencies of transformer components to identify potential issues.

5. **Partial Discharge Analysis**

   Partial discharge (PD) activity is a common indicator of insulation degradation.

   PD Measurement:

   - **Pulse Magnitude**: Measuring the magnitude of discharge pulses to assess severity.
   - **Phase Resolved PD Patterns**: Analyzing the patterns of PD activity relative to the AC voltage cycle to identify the type of insulation defect.

   Example Calculation:

   - **Apparent Charge (q)**: q = U·Iωq = \frac{U \cdot I}{\omega}q = ωU·I Where UUU is the voltage, III is the current, and ω\omegaω is the angular frequency.

6. **Load and Overload Analysis**

   Analyzing the loading conditions of the transformer is essential to understand potential overloading issues.

   Load Profile Analysis:

   - **Peak Load Calculation**: Identifying periods of peak load and comparing them to the transformer's rated capacity.
   - **Load Duration Curve**: Analyzing the duration for which the transformer operates at various load levels.

   Example Calculation:

   - **Loading Factor (LF)**:

     LF = Average Load/Rated Capacity

     This ratio helps determine whether the transformer is consistently operating within safe limits.

7. **Insulation Life Estimation**

   The life expectancy of transformer insulation is a critical factor in predicting transformer lifespan.

   - **Life Expectancy Calculation**:
     - **Thermal Aging Models**: Using models like the Arrhenius equation to estimate the remaining life of the insulation based on temperature history.
   - **Example Calculation**:
     - **Insulation Life (L)**:

       $L = L0 \times e - TB$

       Where L0 is the initial life expectancy, B is a material constant, and T is the operating temperature.

Key Consideration

(1) Transformer Design and Construction of 12.5 MVA Power Transformers

1. Core Design

Description: The core of a transformer is made of laminated silicon steel sheets that help to reduce core losses and provide a path for the magnetic flux.

Materials Used:

Silicon Steel Laminations: These are used to minimize core losses and improve efficiency. The laminations are coated with an insulating layer to reduce eddy currents.

Insulating Paper: Used between laminations to prevent electrical shorts.

Potential Weaknesses:

Insulation Degradation: Over time, insulation between laminations can degrade due to thermal or environmental stresses.

Core Saturation: If the core design does not accommodate high flux densities, it may saturate, leading to inefficiencies and overheating.

Recommendations:

Use High-Quality Materials: Ensure that silicon steel laminations are of high quality and properly insulated.

Design for Flux Density: Design the core to handle expected flux densities without reaching saturation.

2. Winding Design

Description: Transformers have primary and secondary windings made of copper or aluminum wire, wound around the core. These windings transfer electrical energy between the primary and secondary circuits.

Materials Used:

Copper or Aluminum Wire: Chosen based on cost and conductivity requirements. Copper is more conductive but more expensive than aluminum.

Insulation: Insulating paper, enamel coatings, and pressboard are used to isolate the windings and prevent electrical faults.

Potential Weaknesses:

Insulation Failure: Insulation can degrade over time due to thermal stress, moisture, or mechanical damage.

Overloading: Excessive current can cause overheating and damage to the windings.

Recommendations:

Use Robust Insulation: Employ high-quality insulation materials to enhance durability.

Monitor Load: Implement protection systems to prevent overloading and overheating.

3. **Cooling System**

Description: Cooling systems maintain the transformer at an optimal operating temperature. They typically include cooling oil, radiators, and fans.

Materials Used:

Cooling Oil: Typically mineral oil or ester-based fluids that dissipate heat and insulate electrical components.

Radiators and Fans: Made of metals like aluminum or steel, these components help to dissipate heat from the oil.

Potential Weaknesses:

Oil Degradation: Cooling oil can degrade over time due to oxidation and thermal stresses.

Cooling System Failures: Failures in the cooling system components, such as clogged radiators or malfunctioning fans, can lead to overheating.

Recommendations:

Regular Oil Analysis: Perform periodic testing of cooling oil to detect signs of degradation or contamination.

Maintain Cooling Equipment: Regularly inspect and clean radiators and fans to ensure efficient operation.

4. **Tank and Enclosure**

Description: The transformer tank houses the core and windings and provides structural support. It is usually made of steel and coated to prevent corrosion.

Materials Used:

Steel: Used for the tank and structural supports, coated with protective layers to resist corrosion.

Protective Coatings: Paints and coatings that protect against environmental factors.

Potential Weaknesses:

Corrosion: Steel tanks are susceptible to corrosion, especially in harsh environments.

Structural Damage: Mechanical impacts or stress can cause structural damage to the tank.

Recommendations:

Use Corrosion-Resistant Coatings: Apply high-quality coatings to protect the steel tank from environmental damage.

Inspect for Damage: Regularly inspect the tank for signs of corrosion or structural damage and address issues promptly.

5. **Bushing and Termination Design**

   Description: Bushings provide the electrical connection between the internal transformer components and the external power lines. They are designed to insulate and support electrical connections.

Materials Used:

Insulating Materials: Typically made from porcelain or composite materials, which offer high insulation resistance.

Conductors: Conductive materials that connect internal windings to external circuits.

Potential Weaknesses:

Insulation Breakdown: Over time, the insulation can degrade due to electrical stresses or environmental conditions.

Mechanical Failures: Bushings can suffer from mechanical damage or fatigue.

Recommendations:

High-Quality Insulators: Use high-quality insulating materials and regularly inspect them for signs of wear or damage.

Regular Testing: Perform electrical and mechanical testing of bushings to ensure they are functioning correctly.

(2) Operational History Analysis for 12.5 MVA Power Transformers

1. **Load Patterns**

   Description: Load patterns refer to how electrical demand fluctuates over time, including peak loads, average loads, and load variations throughout the day and year.

Key Factors:

Peak Loads: Occasional high demand periods can stress the transformer, especially if it operates near its maximum capacity.

Load Cycling: Frequent changes in load can cause thermal cycling, which may accelerate insulation degradation and mechanical wear.

Load Imbalance: Uneven loading between phases can lead to overheating and inefficiencies.

Recommendations:

Monitor Load Trends: Implement load monitoring systems to track and analyze load patterns over time.

Manage Peak Loads: Utilize load management strategies to avoid overloading the transformer during peak periods.

Balance Loads: Ensure load is evenly distributed across phases to prevent overheating and improve efficiency.

Implications:

Prevent Overloading: Proper load management helps avoid overloading, which can lead to overheating and premature failure.

Extend Transformer Life: Balancing loads and managing peak demands reduce thermal stress and extend the lifespan of the transformer.

2. **Voltage Fluctuations**

Description: Voltage fluctuations involve changes in voltage levels that can affect transformer performance and longevity. These can be caused by load changes, system faults, or external disturbances.

Key Factors:

Sag and Swell: Voltage sag (drop) and swell (increase) can stress the transformer insulation and lead to failures.

Harmonics: Distorted voltage waveforms due to harmonics can cause additional heating and insulation stress.

Recommendations:

Voltage Regulation: Implement voltage regulation equipment and devices to maintain stable voltage levels.

Monitor for Harmonics: Use harmonic filters and monitoring tools to reduce the impact of voltage distortion.

Implications:

Reduce Insulation Stress: Maintaining stable voltage levels helps prevent insulation breakdown and transformer damage.

Improve Performance: Proper voltage regulation improves overall transformer performance and reliability.

3. **External Factors**

   Description: External factors include environmental conditions such as weather, pollution, and physical impacts that can influence transformer performance.

Key Factors:

Weather Conditions: Extreme temperatures, high humidity, and precipitation can affect cooling efficiency and insulation performance.

Pollution: Dust, chemical contaminants, and other pollutants can degrade insulation and cooling systems.

Physical Impacts: Vandalism, accidental impacts, and structural stresses can damage the transformer.

Recommendations:

Environmental Protection: Use protective measures such as weatherproof enclosures and filtration systems to shield the transformer from environmental impacts.

Regular Inspections: Conduct regular inspections to identify and address issues caused by pollution or physical damage.

Enhanced Security: Implement security measures to prevent vandalism and accidental damage.

Implications:

Enhance Durability: Protecting the transformer from environmental factors and physical impacts increases its durability and reduces the risk of failure.

Improve Reliability: Regular inspections and environmental protections ensure reliable operation and prevent potential issues.

4. **Historical Performance Data**

   Description: Analyzing historical performance data involves reviewing past operational records, maintenance logs, and failure incidents to identify patterns and recurring issues.

Key Factors:

Maintenance Records: Review past maintenance activities to ensure that all recommended procedures were followed and identify any recurring issues.

Failure Incidents: Analyze previous failures to understand their causes and implement corrective measures.

Recommendations:

Review Maintenance Logs: Regularly review and update maintenance practices based on historical performance data.

Analyze Failure Trends: Use failure analysis to identify root causes and implement preventive measures.

Implications:

Inform Maintenance Strategies: Historical performance data helps in refining maintenance strategies and addressing recurring issues.

Enhance Predictive Maintenance: Data-driven insights support predictive maintenance practices, reducing unexpected failures.

(3) Maintenance Practices to Prevent Failure of 12.5 MVA Power Transformers

1. **Maintenance Schedule**

   Description: A well-defined maintenance schedule outlines the frequency and types of maintenance activities required for transformer upkeep.

Evaluation Factors:

Routine Inspections: Scheduled inspections to check the condition of critical components such as insulation, cooling systems, and bushings.

Preventive Maintenance: Regularly planned activities, including cleaning, lubrication, and part replacement, aimed at preventing failures.

Predictive Maintenance: Techniques such as Dissolved Gas Analysis (DGA) and Partial Discharge (PD) testing to predict potential failures based on real-time data.

Potential Gaps:

Inadequate Frequency: Inspections or maintenance tasks that are scheduled too infrequently may miss early signs of degradation.

Reactive Maintenance: Relying primarily on reactive maintenance instead of preventive or predictive approaches can lead to unplanned outages.

Recommendations:

Regular Review: Continuously review and adjust the maintenance schedule based on operational data and transformer condition.

Implement Predictive Tools: Integrate predictive maintenance tools to anticipate and address potential issues before they cause failures.

Implications:

Early Detection: A well-structured maintenance schedule helps in the early detection of issues, reducing the risk of unexpected failures.

Improved Reliability: Regular and predictive maintenance practices enhance the overall reliability and performance of the transformer.

2. **Inspection Practices**

   Description: Inspection practices involve examining transformer components for signs of wear, damage, or deterioration.

Evaluation Factors:

Visual Inspections: Regular visual checks for physical damage, leakage, or corrosion.

Electrical Testing: Routine testing of insulation resistance, power factor, and transformer health indicators.

Thermal Imaging: Use of thermal cameras to detect overheating components and anomalies.

Potential Gaps:

Inconsistent Procedures: Inconsistent or incomplete inspection procedures may lead to missed issues.

Limited Scope: Focusing only on visible components may overlook internal or less obvious problems.

Recommendations:

Standardize Procedures: Develop and enforce standardized inspection procedures to ensure thorough and consistent checks.

Comprehensive Inspections: Expand the scope of inspections to include internal components and use advanced diagnostic tools.

Implications:

Thorough Checks: Consistent and comprehensive inspections increase the likelihood of detecting potential problems early.

Reduced Downtime: Early detection of issues helps in minimizing unplanned downtime and maintenance costs.

3. **Maintenance Documentation**

   Description: Proper documentation involves recording all maintenance activities, inspections, and repairs performed on the transformer.

Evaluation Factors:

Record Keeping: Detailed logs of maintenance activities, including dates, performed tasks, and observed conditions.

Data Analysis: Analysis of maintenance records to identify patterns or recurring issues.

Potential Gaps:

Incomplete Records: Incomplete or inaccurate documentation can hinder the identification of trends and recurring problems.

Lack of Analysis: Failure to analyze maintenance data may result in missed opportunities for process improvements.

Recommendations:

Maintain Detailed Logs: Ensure accurate and comprehensive documentation of all maintenance activities.

Analyze Trends: Regularly analyze maintenance records to identify and address recurring issues or potential areas for improvement.

Implications:

Informed Decisions: Detailed and accurate documentation supports informed decision-making and continuous improvement.

Trend Identification: Analyzing data helps in identifying and addressing systemic issues, improving overall reliability.

4. **Training and Competency**

Description: Training and competency involve ensuring that maintenance personnel are skilled and knowledgeable about transformer maintenance and operation.

Evaluation Factors:

Training Programs: Regular training programs for maintenance staff on transformer technology, procedures, and safety.

Certification and Skills: Ensuring that personnel have the necessary certifications and skills to perform maintenance tasks effectively.

Potential Gaps:

Insufficient Training: Lack of ongoing training or outdated knowledge can lead to improper maintenance practices.

Skills Gaps: Personnel without the required skills may struggle to identify or address complex issues.

Recommendations:

Ongoing Training: Implement regular training programs to keep maintenance personnel updated on best practices and new technologies.

Certification: Ensure that maintenance staff are certified and skilled in transformer maintenance and repair.

Implications:

Effective Maintenance: Well-trained personnel perform maintenance tasks more effectively, reducing the risk of errors and improving transformer reliability.

Enhanced Safety: Proper training ensures that maintenance activities are conducted safely and efficiently.

(4) Diagnostic Data for Preventing Failure of 12.5 MVA Power Transformers

1. Dissolved Gas Analysis (DGA)

Description: DGA is a key diagnostic technique that involves analyzing gases dissolved in transformer oil to detect signs of internal faults.

Diagnostic Tools:

Gas Chromatographs: Devices used to separate and analyze different gases in the oil.

DGA Sensors: Sensors that measure gas concentrations and provide data on the condition of the transformer.

Key Data Indicators:

Gas Concentrations: Levels of gases such as hydrogen (H2), methane (CH4), ethane (C2H6), and acetylene (C2H2) indicate specific fault types (e.g., overheating, arcing).

DGA Ratios: Ratios such as the Rogers ratio or the Duval triangle can help in diagnosing the severity and type of fault.

Recommendations:

Regular Testing: Perform DGA at scheduled intervals to monitor gas levels and detect changes in gas concentrations.

Trend Analysis: Analyze trends in gas concentrations over time to identify developing issues before they escalate.

Implications:

Early Fault Detection: DGA helps in identifying faults like overheating or electrical discharges early, reducing the risk of catastrophic failures.

Preventive Maintenance: Allows for timely maintenance and repairs based on diagnostic data, improving transformer reliability.

2. Partial Discharge (PD) Testing

Description: PD testing involves measuring partial discharge activity within the transformer to detect insulation defects.

Diagnostic Tools:

PD Detectors: Instruments that measure partial discharge signals in the transformer insulation system.

Ultrasonic Sensors: Used to detect high-frequency acoustic signals generated by partial discharges.

Key Data Indicators:

PD Magnitude and Location: The intensity and location of partial discharges can indicate insulation weaknesses or defects.

PD Patterns: Analyzing the patterns and trends of partial discharge activity helps in diagnosing insulation problems.

Recommendations:

Periodic Testing: Conduct PD testing regularly to monitor insulation condition and detect early signs of deterioration.

Detailed Analysis: Perform detailed analysis of PD signals to accurately diagnose insulation faults and plan corrective actions.

Implications:

Insulation Integrity: Early detection of insulation problems through PD testing helps prevent major failures and extend transformer life.

Targeted Maintenance: Enables targeted maintenance and repairs based on precise fault localization.

3. Power Factor Testing

Description: Power factor testing measures the efficiency of the transformer's insulation system and helps in identifying insulation degradation.

Diagnostic Tools:

Power Factor Testers: Devices that measure the power factor of the transformer insulation.

Insulation Resistance Testers: Instruments used to measure insulation resistance and power factor.

Key Data Indicators:

Power Factor Values: Increased power factor values indicate degraded insulation and potential issues.

Insulation Resistance: Changes in insulation resistance can signal insulation deterioration.

Recommendations:

Routine Measurement: Perform power factor testing as part of routine maintenance to monitor insulation condition.

Analyze Trends: Track power factor trends over time to detect insulation degradation early.

Implications:

Insulation Condition: Helps assess the condition of insulation and identify potential problems before they lead to failures.

Maintenance Planning: Provides data for planning maintenance activities to address insulation issues.

4. **Thermal Imaging**

Description: Thermal imaging uses infrared cameras to detect temperature variations in the transformer, identifying potential hotspots and thermal issues.

Diagnostic Tools:

Infrared Cameras: Devices that capture thermal images and measure temperature distributions.

Thermal Analysis Software: Software used to analyze thermal images and identify hotspots.

Key Data Indicators:

Temperature Hotspots: Areas with elevated temperatures may indicate issues such as poor cooling, electrical faults, or loose connections.

Heat Distribution Patterns: Analyzing heat distribution helps in identifying areas of concern and potential problems.

Recommendations:

Regular Inspections: Use thermal imaging regularly to monitor temperature distribution and detect overheating issues.

Focus on Critical Areas: Pay special attention to components prone to overheating, such as connections and cooling systems.

Implications:

Heat Management: Identifying and addressing hotspots helps in managing heat and preventing thermal-related failures.

Improved Safety: Thermal imaging enhances safety by detecting potential overheating issues before they cause damage.

5. **Sweep Frequency Response Analysis (SFRA)**
   Description: SFRA involves analyzing the frequency response of the transformer to detect mechanical and electrical issues, such as winding deformation or core problems.

Diagnostic Tools:

SFRA Analyzers: Devices that measure the frequency response of the transformer and provide data on mechanical and electrical integrity.

Key Data Indicators:

Frequency Response Curves: Changes in response curves indicate possible mechanical deformations or winding issues.

Comparison with Baseline: Comparing current response with baseline data helps in identifying deviations and potential problems.

Recommendations:

Baseline Data: Establish baseline frequency response data for comparison with future measurements.

Regular Testing: Conduct SFRA testing at scheduled intervals to monitor transformer condition.

Implications:

Mechanical Integrity: Helps detect mechanical issues such as winding movement or core problems, allowing for timely intervention.

Preventive Maintenance: Provides valuable data for preventive maintenance and repairs.

An Investigation on the Failure.pdf

Parag

ORIGINALITY REPORT

11%	7%	6%	6%
SIMILARITY INDEX	INTERNET SOURCES	PUBLICATIONS	STUDENT PAPERS

PRIMARY SOURCES

1	tudr.thapar.edu:8080 Internet Source	1%
2	Kumar, E. Suresh, and Bijan Sarkar. "Impact of wind and shading on energy contribution by photovoltaic panels with axis tracking system", 2013 Annual International Conference on Emerging Research Areas and 2013 International Conference on Microelectronics Communications and Renewable Energy, 2013. Publication	1%
3	files.thapar.edu Internet Source	<1%
4	Submitted to Thapar University, Patiala Student Paper	<1%
5	hdl.handle.net Internet Source	<1%
6	Submitted to Engineering Institute of Technology Student Paper	<1%